


Pentarch Forestry

Pollution Incident Response Management Plan Narooma



Page 1 of 33 Next review date: 02/10/2025





Once printed this document is uncontrolled and information only. Refer electronic copy on the Pentarch Group intranet site for controlled version Document owner: HSE Manager Revision: 11.0

Page 2 of 33 Review date: 03/10/2023 Next review date: 02/10/2025



PIRMP Site Assessment Sheet

LIST OF POLLUTING SUBSTANCE STORAGES/USES AT SITE INITIAL ASSESSMENT						
(all Chemicals listed in this sheet are to be subjected to a risk assessment)						
Site Name:	Responsible Person:	Edition Date:				
Narooma Timber Mill Shaun Jorgensen 16/08/2012						
		Revised: 15/09/2022				

PIRMP Drill

- Conducted 22:11:12 (incident #1 / 2 / 3 / 9)
- Conducted 11:06:14 (incident #1 / 2 / 3 / 5 / 6 / 11)
- Conducted 07:10:15(incident#2)
- Conducted 12/10/16 (incident #4 / 7 / 8)
- Conducted 09/10/17 (incident #4 / 7 / 8)
- Conducted 13/11/18 (incident #10)
- Conducted 21/11/19 (incident #5)
- Conducted 15/09/20 (incident #4 / 7 /8)
- Conducted 1/11/21 (incident #5)
- Conducted 17/11/22(incident #10)
- Conducted 28/9/2023 (Incident #9)

Name /	Covered under	Max	Location of	Мар	Need for	Current controls	See Risk Ass &		
description	Hazardous	amount	storage	reference	early		PIRMP Response		
	Chemicals/MSDS?	stored			warning ¹		Action (see Below)		
CHEMICALS/FUELS	CHEMICALS/FUELS/LUBRICANTS (raw materials and products which can cause pollution)								
Diesel	Class 3	3000 ltrs	Oil Storage	Ref No 1	N/A	Bunding	Incident # 1-3		
			Shed			• PMP			
						 Training 			
						 Spill Kits 			

¹ Early warnings relate to informing neighbours who may be affected by the emission of this substance. If this substance is of a type and quantity which may reach neighbours then early warning assessment of actions is required to be undertaken.

Once printed this document is uncontrolled and information only. Refer electronic copy on the Pentarch Group intranet site for controlled version

Document owner: HSE Manager Revision: 11.0 Page 3 of 33 Review date: 03/10/2023 Next review date: 02/10/2025



Review date: 03/10/2023

POLLUTION INCIDENT RESPONSE MANAGEMENT PLAN

Name / description	Covered under Hazardous Chemicals/MSDS?	Max amount stored	Location of storage	Map reference	Need for early warning ¹	Current controls	See Risk Ass & PIRMP Response Action (see Below)
						 SOP Inductions Fire Fighting Equipment Security Emergency Response Sand/Sawdust Ground Water Monitoring Wells 	
Oils/Solvents	Class 3	Packaged goods up to 1500 ltrs	Oil Storage Shed	Ref No 1	N/A	 Bunding PMP Training Flammable Cabinet Spill Kits Inductions Fire Fighting Equipment Security Emergency Response Sand/Sawdust Remediator – bio remediation of soils. Ground Water Monitoring Wells 	Incident # 4
Lubricants, Gases	Class 2	Variable. Max at any time 500L.	Maintenance Workshop	Ref No 2	N/A	 Fire Extinguishers Concrete Floor Enclosed Shed Containment Cages 	No Incident Potential

Once printed this document is uncontrolled and information only. Refer electronic copy on the Pentarch Group intranet site for controlled version

Document owner: HSE Manager

Revision: 11.0

Page 4 of 33 Next review date: 02/10/2025



POLLUTION INCIDENT RESPONSE MANAGEMENT PLAN

Name / description	Covered under Hazardous Chemicals/MSDS?	Max amount stored	Location of storage	Map reference	Need for early warning ¹	Current controls	See Risk Ass & PIRMP Response Action (see Below)
						and flammable storage cabinet.	
Oils/Fuel	Class 3	Residuals- equipment drained	Redundant Plant and Equipment (Graveyard)	Ref No 3	N/A	 Audits/Inspections Oils/Fuel drained prior to storage Remediator Bunding 	No Incident Potential
MATERIALS (e.g.	stockpiles, silos, bulk s	solids etc)					
Log Stock Pile	N/A	Variable Max 2000tonne	Dedicated on site	Ref No 4	Local Rural Fire Brigade	 Emergency fire equipment. Maintain manageable levels Log stock takes. Security 	Incident # 5
Woodchip	Refer to Boral's MSDS on Woodchip	Variable Max 500m3	Dedicated on site	Ref No 5	Local Bush Fire Brigade	 Emergency fire equipment Maintain manageable levels Security 	Incident # 5
Residue Waste	N/A	Variable. Max 100m3	Dedicated on site	Ref No 6	Local Bush Fire Brigade	 Emergency fire equipment Maintain manageable levels Security 	Incident # 5
AQUEOUS (e.g. d	ams, wastewater tank	s, other wate	r storage area)	·	•		<u>'</u>
Dam 1 (Sediment)	N/A	Variable		Ref No 7	N/A	Continue to irrigate to lower yard to maintain dam levels.	Incident # 6

Once printed this document is uncontrolled and information only. Refer electronic copy on the Pentarch Group intranet site for controlled version

Document owner: HSE Manager

Revision: 11.0

Document owner: HSE Manager Revision: 11.0 Page 5 of 33
Review date: 03/10/2023 Next review date: 02/10/2025



POLLUTION INCIDENT RESPONSE MANAGEMENT PLAN

PENTAR	
FOREST	KT

Name / description	Covered under Hazardous Chemicals/MSDS?	Max amount stored	Location of storage	Map reference	Need for early warning ¹	Current controls	See Risk Ass & PIRMP Response Action (see Below)
Dam 2	N/A	Variable		Ref No 8	N/A	Sediment barrier.Continue to irrigate to	Incident # 6
(Sediment)						lower yard to maintain dam levels. • Sediment barrier.	
Dam 3 (Sediment)	N/A	Variable		Ref No 9	N/A	 Continue to irrigate to yard spray to maintain dam level. Ensure pumps are maintained through scheduled maintenance Sediment barrier 	Incident # 6
Ground Water Monitoring Wells	N/A	N/A	Site	N/A	N/A	Annual water monitoring.	Incident # 11
Storm Water Drains	N/A	Variable	Site	N/A	N/A	 Straw Bales Rubber and Earthen Berms Audits and Inspections 	Incident # 6
SUBSTANCES IN PI	ROCESSES (substance	s which could	be emitted fro	m operationa	l process i.e. tr	eatment plants, vehicles etc)	
Mobile Plant (onsite)	Class 3	Up to 6 mobile plant on site	Dedicated on site	N/A	N/A	 Spill Kits Pre start checks PMP Training Emergency Response Sand/Sawdust Remediator – bio remediation of soils. 	Incident # 7
Mobile Plant	Class 3	Variable	Variable	N/A	N/A	Spill Kits	Incident # 8

Once printed this document is uncontrolled and information only. Refer electronic copy on the Pentarch Group intranet site for controlled version

Document owner: HSE Manager

Revision: 11.0

Document owner: HSE Manager Revision: 11.0 Page 6 of 33
Review date: 03/10/2023 Next review date: 02/10/2025



POLLUTION INCIDENT RESPONSE MANAGEMENT PLAN

Name / description	Covered under Hazardous Chemicals/MSDS?	Max amount stored	Location of storage	Map reference	Need for early warning ¹	Current controls	See Risk Ass & PIRMP Response Action (see Below)
Contractor/visitor			Locations			 Pre start checks Training Inductions Emergency Response Sand/Sawdust Remediator – bio remediation of soils. 	
Car Parking up to 20 vehicles	Class 3	Variable	Site Office	Ref No 10	N/A	 Spill Kits Training Emergency Response Sand/Sawdust Remediator – bio remediation of soils. 	Incident # 9
Traffic Areas (dust, chem. leaks &loss	Class 3	N/A	Dedicated on site	N/A	N/A	Training.Dust suppression system/water tank with pump.	Incident # 10

Page 7 of 33

Next review date: 02/10/2025



IMPACT ON NEIGHBOURS ASSESSMENT – EARLY WARNINGS									
Site Name: Narooma Responsible Person: Date: 15/9/2022 Shaun Jorgensen Site Manager									
Incident type/description	External Release (air, waterway etc)	Neighbors impacted/extent of impact	Communication methods Early warnings		Actions and other cor (e.g. posting on website, co				
N/A									

EMERGENCY DRILLS CONDUCTED

Date	Practice Drill	Type of Drill	Rating 1-5 on	Comment
	Completed		Effectiveness	
06/08/2014	06/08/14	Fire (Wormald)	5 Highly Effective	Minimal Recommendations
11/06/2014	11/06/14	Incident #1,2,3	4 Effective	Train Emergency Response Team on use of spill
		Shaun Jorgensen – Site		kit by 30 th Sept. 2014
		Supervisor		Responsible – Shaun Jorgensen
		Steven Kostiuk – HSE		Follow Up – HSE Advisor
11/06/2014	11/06/14	Incident #5	4 Effective	No actions required
		Shaun Jorgensen – Site		
		Supervisor		
		Steven Kostiuk – HSE		
11/06/2014	11/06/14	Incident #6,11	5 Highly Effective	Dams are to be monitored and inspected for
		Shaun Jorgensen – Site		levels and integrity.
		Supervisor		Pumps are to be maintained through scheduled
		Steven Kostiuk – HSE		maintenance.
				Annual ground water monitoring program.
09/10/2015	07/10/15	Incident # 12	4 Effective	Fit for Purpose size decanting containers
		Shaun Jorgensen- Site		Ensure Spills Kits are maintained (free from
		Supervisor		spiders)

Once printed this document is uncontrolled and information only. Refer electronic copy on the Pentarch Group intranet site for controlled version

Document owner: HSE Manager

Review date: 03/10/2023

Page 8 of 33 Next review date: 02/10/2025



POLLUTION INCIDENT RESPONSE MANAGEMENT PLAN

Date	Practice Drill Completed	Type of Drill	Rating 1-5 on Effectiveness	Comment
				Materials used in spills response from kit are listed to ensure re-stocking.
12/10/2016	12/10/16	Incident # 4, 7,8 Steven Kostiuk – Acting Site Supervisor Les Medbury – HSR Mark English – Fitter	4 Effective	Ensure Spills Kits are maintained (free from spiders) Regular inspections of maintenance areas and drains.
09/10/2017	09/10/2017	Incident # 4, 7,8 Shaun Jorgensen Site Manager Les Medbury- HSR Mark English- Fitter	4 Effective	Regular inspections of maintenance areas and drains. Ensure Spill Kits stock levels are maintained and clear access to Spill Kits at all times.
13/11/2018	13/11/2018	Incident #10 Shaun Jorgensen Luke Nunn Les Medbury Nathaniel Rae	4 Effective	Ensure water truck is used more frequently in dryer conditions. Employees to be made aware of all sprinkler shut off /turn on valves around site.
21/11/2019	21/11/2019	Incident #5 Shaun Jorgensen Les Medbury, Nathaniel Rae Steve Ilitch	4 Effective	Ensure water truck is in a fit for purpose use at all times
15/09/2020	15/09/2020	Incident # 4,7,8 Steve Ilitch-Leading hand Amanda Gregor- Data Operations Les Medbury- Safety officer	4 Effective	Ensure Spill Kits stock levels are maintained and clear access to Spill Kits at all times. Regular inspections of maintenance areas and drains.
1/11/2021	1/11/2021	Incident #5 Shaun Jorgensen	4 Effective	Ensure fire prevention kept clear from obstructions and in test date at all times. C

Once printed this document is uncontrolled and information only. Refer electronic copy on the Pentarch Group intranet site for controlled version

Document owner: HSE Manager

Revision: 11.0

Document owner: HSE Manager Revision: 11.0 Page 9 of 33
Review date: 03/10/2023 Next review date: 02/10/2025

Review date: 03/10/2023

POLLUTION INCIDENT RESPONSE MANAGEMENT PLAN

Date	Practice Drill	Type of Drill	Rating 1-5 on	Comment
	Completed		Effectiveness	
		Steve Ilitch – Leading hand		
		Rod Pratt – Fitter		
		Ben Nunn – App Fitter		
17/11/2022	15/09/2022	Shaun Jorgensen	4 Effective	
		Steve Ilitch		
		Ben Nunn		
		Rod Pratt		
28/9/2023	28/9/2023	Steve Ilitch	4 Effective	
		Ben Nunn		
		Robert Tudor		

Emergency Response Personnel Training

Date	Names	Training Date	PIRMP Drill	Comment
07/10/2015	Shaun Jorgensen Les Medbury	07/10/15	07/10/15	
29/09/2016	Mark English Les Medbury Shaun Jorgensen Nathaniel Rae	29/09/16	12/10/16	Environmental Awareness Training was conducted by Greg Ninnes on the 29/09/16
09/10/2017	Shaun Jorgensen Paul Riley	09/10/2017	09/10/2017	
13/11/2018	Mark English Les Medbury, Luke Nunn Nathaniel Rae	13/11/2018	13/11/2018	
21/11/2019	Shaun Jorgensen Les Medbury,	21/11/2019	21/11/2019	

Once printed this document is uncontrolled and information only. Refer electronic copy on the Pentarch Group intranet site for controlled version

Document owner: HSE Manager

Revision: 11.0

Page 10 of 33 Next review date: 02/10/2025



POLLUTION INCIDENT RESPONSE MANAGEMENT PLAN

Date	Names	Training Date	PIRMP Drill	Comment
	Nathaniel Rae Steve Ilitch			
15/11/2020	Les Medbury Amanda Gregor Steve Ilitch	15/09/2020	15/09/2020	Online Training Environmental Management Compliance, Obligations and Risk Management.
1/11/2021	Shaun Jorgensen Steve Ilitch Ben Nunn Rod Pratt	1/11/2021	1/11/2021	
25/10/2022	Shaun Jorgensen Steve Ilitch Ben Nunn Rod Pratt	25/10/2022	15/09/2022	Environmental Training Awareness training and spills kit conducted by Attila Ballaz and Greg Ninness

RISK ASSESSMENT MATRIX

	TABLE 1: Measures of Consequence					
Value	Description	Impact				
1	Incidental	No discernable impact or measurable impairment on habitat, species or natural environment (air, water, land).				
2	Minor	Localised and measurable short term impact on habitat, species or natural environment.				
3	Moderate	Localised and measurable medium term impact on habitat, species or natural environment.				
4	Major	Extensive and measurable medium term impact on habitat, species, or natural environment.				
5	Severe	Destruction of important populations of habitat, species, or natural environment.				

Once printed this document is uncontrolled and information only. Refer electronic copy on the Pentarch Group intranet site for controlled version

Document owner: HSE Manager

Revision: 11.0

Review date: 03/10/2023



PENTARCH FORESTRY NAROOMA POLLUTION INCIDENT RESPONSE MANAGEMENT PLAN

	TABLE 2: Qualitative measurement of how likely or probable the consequence will occur					
Level	Level Likelihood Description					
1	Rare	The consequence is not expected in Pentarch/ Has never been heard of in the Industry.				
2	Unlikely	The consequence is possible in Pentarch/ Has occurred in the Industry.				
3	Possible	The consequence is possible at a Pentarch workplace at some time in the foreseeable future (next 10 years) / Has happened at Pentarch in past 10 years / Occurs annually within the Industry.				
4	Likely	The event is expected at a site/local level in the foreseeable future (next few years) / Occurs within Pentarch more than once per year.				
5	Almost Certain	The event is expected to occur several times a year at a site/local level.				

	TABLE 3: Qualitative Risk Matrix – Levels of Risk							
Consequence Likelihood	Incidental (1)	Minor (2)	Moderate (3)	Major (4)	Severe (5)			
Almost Certain (5)	M (8)	H (14)	E (20)	E (22)	E (25)			
Likely (4)	M (7)	M (10)	H (16)	E (21)	E (24)			
Possible (3)	L (3)	M (9)	H (15)	H (18)	E (23)			
Unlikely (2)	L (2)	L (5)	M (11)	H (17)	Н (19)			
Rare (1)	L (1)	L (4)	L (6)	M (12)	M (13)			

Once printed this document is uncontrolled and information only. Refer electronic copy on the Pentarch Group intranet site for controlled version

Document owner: HSE Manager

Review date: 03/10/2023

Page 12 of 33 Next review date: 02/10/2025



RISK ASSESSMENT on POTENTIAL IMPACTS

Narooma				_	nsible Persperations				
Name of pollutant/c hemicals	Description of Hazard / Incident leading to hazard	Consequence	Likely hood	Risk	Impact on Neigh- bours ²	Control Measures Corrective Action Coverage under other Plans	Responsible Person	Next Review Date	
Diesel	Incident #1 Catastrophic failure of one/both above ground tanks	1	2	L2	N/A	Consequence: (incidental): Failure resulting in loss of all or substantial volume of tanks would be captured entirely by existing primary bund with no release to soil or water. Likelihood: (unlikely): Due to location within bund, damage to tanks is unlikely to occur from external equipment. In addition tanks are maintained in good structural integrity with low risk of failure through corrosion.	As per PIRMP action plan	15/09/24	
	Incident #2 Loss of diesel outside bund during refuelling/fuelling operations.	1	3	L3	N/A	Consequence: (incidental): Failure resulting in loss/leakage from fuelling or re-fuelling from hose, nozzle or plant/equipment would be captured by a secondary bund or spill kill with minimal release to soil. Likelihood: (possible): Due to location within the bund an incident while re-fuelling and fuelling is likely to occur on some occasions. Hoses and refuelling equipment are maintained with low risk of failure.	As per PIRMP action plan	15/09/24	
	Incident #3 Loss of fuel within bunded area with leaking or open drain valve	1	2	L2	N/A	Consequence: (incidental): Failure resulting in loss of all or substantial volume of tanks would be captured entirely by primary bund with minimal release to soil. Likelihood: (unlikely): Drain valve, hoses and refuelling equipment are maintained in good structural integrity with low risk of failure The drain valve is locked at all times.	As per PIRMP action plan	15/09/24	

² If the incident may impact on neighbours then it will need to trigger the early warnings assessment and actions

Once printed this document is uncontrolled and information only. Refer electronic copy on the Pentarch Group intranet site for controlled version

Document owner: HSE Manager
Review date: 03/10/2023
Review date: 03/10/2023
Review date: 03/10/2025



POLLUTION INCIDENT RESPONSE MANAGEMENT PLAN

Oils/	Incident #4	1	2	L2	N/A	Consequence :(incidental): Failure resulting in loss of oils/solvents from	As per	15/09/24
Solvents	Loss of oils solvents					packaged goods would be captured entirely by existing primary bund	PIRMP	
	inside bund during					with no release to soil or water.	action plan	
	delivery and or use					Likelihood: (unlikely): Due to location within the bund, spillage during		
						delivery and use is unlikely to occur. In addition hoses and decanting		
						equipment are maintained in good structural integrity with low risk of failure.		
Log, Wood	Incident #5.	2	2	L5	Υ	Consequence: (minor): Fire from stock piles or internal mill works	As per	15/09/24
chip &	Spontaneous					causing loss off assets creating substantial smoke around the area.	PIRMP	
Residue	combustion or					Likelihood: (unlikely): Stockpiles are maintained to a manageable level	action plan	
stockpiles	ignited fire					along with emergency equipment inspected on a monthly basis. Hot		
						works SWMS and permits utilised to eliminate potential risks.		
Dams 1-3	Incident #6	2	2	L5	N/A	Consequence: (minor): Catastrophic failure of one or more sediment	As per	15/09/24
	Catastrophic failure					dams are likely to result in off-site impacts to water courses which	PIRMP	
	of one or more					would predominantly reduce water quality over a short period of time.	action plan	
	tannin dams					As such, impact to the environment/human health is not considered to		
	releasing large					be significant.		
	volumes of tannin					Likelihood: (unlikely): Dams are frequently monitored and inspected for		
	water into on-site					levels and integrity.		
	and off-site water					Risk Assessment = Moderate Vs Unlikely = L (2)		
	courses (i.e. creek).					Note: For PIRMP purposes overflow events during extreme wet		
						weather will be reported under POEO Licence obligations and not		
0.0 = -11 =	1	1	1	1.2	N.I	Immediate Reporting.	A	45/00/24
Mobile	Incident #7	1	2	L2	N	Consequence: (incidental): Failure from fuel tank or hydraulic hoses would be maintain to a small localised area on site.	As per	15/09/24
Plant	Mobile plant, hydraulic hose or						PIRMP action plan	
	fuel tank failure					Likelihood :(unlikely): Hose or fuel tank failure from mobile plant would be minimal as prestart and regular maintenance programs are in place	action plan	
	Tuer talik fallure					to capture and prevent such occurrences. Spills kits also maintain and		
						available in various areas.		
						Remediator – bio remediation of soils.		
						Remediator – bio remediation of soils.		

Once printed this document is uncontrolled and information only. Refer electronic copy on the Pentarch Group intranet site for controlled version

Document owner: HSE Manager

Revision: 11.0

Review date: 03/10/2023

Page 14 of 33 Next review date: 02/10/2025



POLLUTION INCIDENT RESPONSE MANAGEMENT PLAN

Mobile plant/ Contractor, Visitor	Incident # 8 Mobile plant, hydraulic hose or fuel tank failure	1	2	L2	N	Consequence: (incidental): Failure from fuel tank or hydraulic hoses would be maintain to a small localised area on site. Likelihood: (unlikely): Hose or fuel tank failure from mobile plant would be minimal as prestart and regular maintenance programs are in place to capture and prevent such occurrences. Spills kits also maintain and available in various areas. Inductions for all contractors demonstrating their accountabilities and responsibilities for reporting environmental incidents. Remediator – bio remediation of soils.	As per PIRMP action plan	15/09/24
Car Park	Incident # 9 Ruptured fuel tank	1	2	L2	N	Consequence: (incidental): Failure from fuel tank or hydraulic hoses would be maintain to a small localised area on site. Likelihood: (unlikely): Hose or fuel tank failure from mobile plant would be minimal as prestart and regular maintenance programs are in place to capture and prevent such occurrences. Spills kits also maintain and available in various areas	As per PIRMP action plan	15/09/24
Traffic areas (dust)	Incident # 10 Surface dust from mobile plant	1	2	L2	Y	Consequence: (incidental): Dust created form continuous mobile plant operations across site Likelihood:(unlikely): Main areas watered with fire hoses in high wind conditions	As per PIRMP action plan	15/09/24
Ground Water Monitoring	Incident #11 Migration of pollutants off site	3	2	M11	Y	Consequence: (moderate) Contamination of local waterways or ground water aquifers Likelihood: (unlikely) Annual ground water monitoring program implemented	As per PIRMP action plan	15/09/24

Page 15 of 33 Next review date: 02/10/2025



PIRMP ACTION PLAN

Incident No 1

Incident No 1	Catastrophic failure of one/both diesel tanks.								
	Actions Required (by Shaun Jorgensen and PIRMP Team):								
	Contact all relevant people/department (refer to Immediate Reporting Contact Sheet)								
	Ensure bunds are capturing full volume of diesel								
	 Ensure bund integrity is sound throughout the entire period of incident (i.e. periodic inspections) 								
	Contact service provider (Caltex No. 1800033111 or Transpacific 02 96007185) to pump-out bund contents								
	Area to be restricted to Emergency Response Personnel								
	Ensure spill kit available for any release from bund								
	If any release from bund onto unsealed soil/surface water - Environmental Consultants to be engaged to investigate and								
	remediate contamination.								
	Repair/replace tanks								
	Refuel tanks								
	Inspect bund for ongoing serviceability								
Alarm raising	Any personnel involved or witnessing incident to report to immediate supervisor and PIRMP actions to be implemented.								
Emergency	Shaun Jorgensen (reporting to Greg Ninness)								
Controller	Call service provider (Shaun Jorgensen staff)								
	Spill Kit manager (Emergency Response Personnel)								
	Periodic inspections and update reporting of site and bund (Shaun Jorgensen)								
Scale of incident	Incident would be restricted to chemical storage area with minimal external impact, however, potential for bund overflow or failure								
	may result in soil and surface water contamination that will require specialist investigation/remediation.								
Evacuate	Only if fire or explosion potential exists. Site Supervisor and any advice provided by Fire Dept as part of attendance after immediate								
	notification.								
Communications	Internal:								
	Operations Manager								
	Greg Ninness HSE Manager								
	External mandatory:								
	Immediate Reporting Contact Sheet to be used								
	External non-mandatory: N/A								

Once printed this document is uncontrolled and information only. Refer electronic copy on the Pentarch Group intranet site for controlled version Document owner: HSE Manager Revision: 11.0

Page 16 of 33 Review date: 03/10/2023 Next review date: 02/10/2025





Rescuer /	As per Site Emergency Plan or Fire Department as part of Immediate Reporting
respondent +	
safety checks	
Rescue + First	As per Site Emergency Plan or Fire Department as part of Immediate Reporting
Aid	
Clean up and	Service Provider to dispose of diesel and advise on required clean-up.
Waste disposal	
Reporting and	See SOPs:
re-preparedness	Incident Management (SOP GRP-OHS-052)

Incident No 2	Loss of Fuel due to filling and refueling from one/both diesel tanks.								
	Actions Required (by Shaun Jorgensen and PIRMP Team):								
	 Contact all relevant people/department (refer to Immediate Reporting Contact Sheet) 								
	Ensure bunds are capturing full volume of diesel								
	Ensure bund integrity is sound throughout the entire period of incident (i.e. periodic inspections)								
	 Contact service provider (Caltex No. 1800033111 or Transpacific 02 96007185) to pump-out bund contents 								
	Area to be restricted to Emergency Response Personnel								
	Ensure spill kit available for any release from bund								
	If any release from bund onto unsealed soil/surface water - Environmental Consultants to be engaged to investigate and								
	remediate contamination.								
	Repair/replace tanks								
	Refuel tanks								
	Inspect bund for ongoing serviceability								
Alarm raising	Any personnel involved or witnessing incident to report to immediate supervisor and PIRMP actions to be implemented.								
Emergency	Shaun Jorgensen (reporting to Greg Ninness)								
Controller	Call service provider (Shaun Jorgensen)								
	Spill Kit manager (Emergency Response Personnel)								
	Periodic inspections and update reporting of site and bund (Shaun Jorgensen)								
Scale of incident	Incident would be restricted to chemical storage area with minimal external impact. However, potential for bund overflow or failure								
	may result in soil and surface water contamination that will require specialist investigation/remediation.								

 $Once \ printed \ this \ document \ is \ uncontrolled \ and \ information \ only. \ Refer \ electronic \ copy \ on \ the \ Pentarch \ Group \ intranet \ site for \ controlled \ version$

Document owner: HSE Manager Revision: 11.0 Page 17 of 33
Review date: 03/10/2023 Next review date: 02/10/2025



POLLUTION INCIDENT RESPONSE MANAGEMENT PLAN

Evacuate	Only if fire or explosion potential exists. Site Supervisor and any advice provided by Fire Dept as part of attendance after immediate
	notification.
Communications	Internal:
	Operations Manager
	Greg Ninness HSE Manager
	External mandatory:
	Immediate Reporting Contact Sheet to be used
	External non-mandatory: N/A
Rescuer /	As per Site Emergency Plan or Fire Department as part of Immediate Reporting
respondent +	
safety checks	
Rescue + First	As per Site Emergency Plan or Fire Department as part of Immediate Reporting
Aid	
Clean up and	Service Provider to dispose of diesel and advise on required clean-up.
Waste disposal	
Reporting and	See SOPs:
re-preparedness	Incident Management (SOP GRP-OHS-052)

Incident No 3

Incident No 3	Failure of drain valve on bund							
	Actions Required (by Shaun Jorgensen and PIRMP Team)							
	 Contact all relevant people/department (refer to Immediate Reporting Contact Sheet) 							
	Ensure bunds are capturing full volume of diesel							
	 Ensure bund integrity is sound throughout the entire period of incident (i.e. periodic inspections) 							
	 Contact service provider (Caltex No. 1800033111 or Transpacific 02 96007185) to pump-out bund contents 							
	Area to be restricted to Emergency Response Personnel							
	Ensure spill kit available for any release from bund							
	 If any release from bund onto unsealed soil/surface water - Environmental Consultants to be engaged to investigate and remediate contamination. 							
	Repair/replace tanks							
	Refuel tanks							

Document owner: HSE Manager Revision: 11.0 Page 18 of 33
Review date: 03/10/2023 Next review date: 02/10/2025



POLLUTION INCIDENT RESPONSE MANAGEMENT PLAN

	Inspect bund for ongoing serviceability
Alarm raising	Any personnel involved or witnessing incident to report to immediate supervisor and PIRMP actions to be implemented.
Emergency	Shaun Jorgensen (reporting to Greg Ninness)
Controller	Call service provider (Shaun Jorgensen)
	Spill Kit manager (Emergency Response Personnel)
	Periodic inspections and update reporting of site and bund (Shaun Jorgensen)
Scale of incident	Incident would be restricted to chemical storage area with minimal external impact. However, potential for bund overflow or failure
	may result in soil and surface water contamination that will require specialist investigation/remediation.
Evacuate	Only if fire or explosion potential exists. Site Supervisor and any advice provided by Fire Dept as part of attendance after immediate
	notification.
Communications	Internal:
	Operations Manager
	Greg Ninness
	External mandatory:
	Immediate Reporting Contact Sheet to be used
	External non-mandatory: N/A
Rescuer /	As per Site Emergency Plan or Fire Department as part of Immediate Reporting
respondent +	
safety checks	
Rescue + First	As per Site Emergency Plan or Fire Department as part of Immediate Reporting
Aid	
Clean up and	Service Provider to dispose of diesel and advise on required clean-up.
Waste disposal	
Reporting and	See SOPs:
re-preparedness	Incident Management

Once printed this document is uncontrolled and information only. Refer electronic copy on the Pentarch Group intranet site for controlled version

Document owner: HSE Manager

Revision: 11.0

Review date: 03/10/2023

Page 19 of 33 Next review date: 02/10/2025



Incident No 4	Loss off oil/solvents, packaged goods
incident NO 4	Actions Required (by Shaun Jorgensen and PIRMP Team):
	Contact all relevant people/department (refer to Immediate Reporting Contact Sheet)
	Ensure bunds are capturing full volume of oil/solvents
	 Ensure bund integrity is sound throughout the entire period of incident (i.e. periodic inspections)
	 Contact service provider (Caltex No. 1800033111or Transpacific 02 96007185) to pump-out bund contents
	Area to be restricted to Emergency Response Personnel
	Ensure spill kit available for any release from bund
	 If any release from bund onto unsealed soil/surface water - Environmental Consultants to be engaged to investigate and
	remediate contamination.
	Inspect bund for ongoing serviceability
Alarm raising	Any personnel involved or witnessing incident to report to immediate supervisor and PIRMP actions to be implemented.
Emergency	Shaun Jorgensen (reporting to Greg Ninness)
Controller	Call service provider (Shaun Jorgensen)
	Spill Kit manager (Emergency Response Personnel)
	Periodic inspections and update reporting of site and bund (Shaun Jorgensen)
Scale of incident	Incident would be restricted to chemical storage area with minimal external impact. However, potential for bund overflow or failure
	may result in soil and surface water contamination that will require specialist investigation/remediation.
Evacuate	Only if fire or explosion potential exists. Site Supervisor and any advice provided by Fire Dept as part of attendance after immediate
	notification.
Communications	Internal:
	Operations Manager
	Greg Ninness
	External mandatory:
	Immediate Reporting Contact Sheet to be used
	External non-mandatory: N/A
Rescuer /	As per Site Emergency Plan or Fire Department as part of Immediate Reporting
respondent +	
safety checks	
Rescue + First	As per Site Emergency Plan or Fire Department as part of Immediate Reporting

Once printed this document is uncontrolled and information only. Refer electronic copy on the Pentarch Group intranet site for controlled version

Document owner: HSE Manager Revision: 11.0 Page 20 of 33
Review date: 03/10/2023 Next review date: 02/10/2025

PENTARCH FORESTRY NAROOMA POLLUTION INCIDENT RESPONSE MANAGEMENT PLAN

Aid	
Clean up and	Service Provider to dispose of diesel and advise on required clean-up.
Waste disposal	
Reporting and	See SOPs:
re-preparedness	Incident Management (SOP GRP-OHS-052)

Incident No 5

Fire in stockpiles of Logs, woodchip and waste residue. Fire in Mill or buildings including workshop.
Actions Required (by Shaun Jorgensen and PIRMP Team)
 Contact all relevant people/departments (refer to Immediate Reporting Contact Sheet)
Area to be restricted to Emergency Response Personnel
 Environmental Consultants to be engaged to investigate and remediate contamination if required
Any personnel involved or witnessing incident to report to immediate supervisor and PIRMP actions to be implemented.
Shaun Jorgensen (reporting to Greg Ninness)
Call Emergencies services
 Periodic inspections and update reporting of site (Shaun Jorgensen)
Incident would be restricted to chemical storage area with minimal external impact. However, potential for bund overflow or failure
may result in soil and surface water contamination that will require specialist investigation/remediation.
Only if fire or explosion potential exists. Site Supervisor and any advice provided by Fire Dept as part of attendance after immediate
notification.
Internal:
Operations Manager
Greg Ninness
External mandatory:
Immediate Reporting Contact Sheet to be used
External non-mandatory: N/A
As per Site Emergency Plan or Fire Department as part of Immediate Reporting
As per Site Emergency Plan or Fire Department as part of Immediate Reporting

Once printed this document is uncontrolled and information only. Refer electronic copy on the Pentarch Group intranet site for controlled version

Document owner: HSE Manager Revision: 11.0 Page 21 of 33
Review date: 03/10/2023 Next review date: 02/10/2025





Clean up and	Service Provider to dispose of diesel and advise on required clean-up.
Waste disposal	
Reporting and	See SOPs:
re-preparedness	Incident Management (SOP GRP-OHS-052)

Incident No 6	Failure of one or more tannin dams
	Actions Required Actions Required (by Shaun Jorgensen and PIRMP Team)
	 Contact all relevant people/department (refer to Immediate Reporting Contact Sheet)
	 Ensure bund integrity is sound throughout the entire period of incident (i.e. periodic inspections)
	Contact local neigbours if going to be in inundated by rise of water
	Area to be restricted to Emergency Response Personnel
	If any release from site onto unsealed soil/surface water - Environmental Consultants to be engaged to investigate and
	remediate contamination if any
	Contact local contractor to rebuild dams immediately
Alarm raising	Any personnel involved or witnessing incident to report to immediate supervisor and PIRMP actions to be implemented.
Emergency	Shaun Jorgensen (reporting to Greg Ninness)
Controller	Call service provider (Shaun Jorgensen)
	Periodic inspections and update reporting of site (Shaun Jorgensen)
Scale of incident	Catastrophic failure of one or more tannin dams are likely to result in off-site impacts to water courses which would predominantly
	reduce water quality over a short period of time. As such, impact to the environment/human health is not considered to be
	significant.
Evacuate	Only if fire or explosion potential exists. Site Supervisor and any advice provided by Fire Dept as part of attendance after immediate
	notification.
Communications	Internal:
	Operations Manager
	Greg Ninness
	External mandatory:
	Immediate Reporting Contact Sheet to be used
	External non-mandatory: N/A

Once printed this document is uncontrolled and information only. Refer electronic copy on the Pentarch Group intranet site for controlled version

Document owner: HSE Manager Revision: 11.0 Page 22 of 33
Review date: 03/10/2023 Next review date: 02/10/2025





Rescuer /	As per Site Emergency Plan or Fire Department as part of Immediate Reporting
respondent +	
safety checks	
Rescue + First	As per Site Emergency Plan or Fire Department as part of Immediate Reporting
Aid	
Clean up and	Consultants to be contacted to advice on required clean-up.
Waste disposal	
Reporting and	See SOPs:
re-preparedness	Incident Management (SOP GRP-OHS-052)

Incident No 7	Mobile plant, hydraulic hose or fuel tank failure
	Actions Required:
	Contact all relevant people/department (refer to Immediate Reporting Contact Sheet)
	Area to be restricted to Emergency Response Personnel
	 Ensure spill kit available for any release from mobile plant & equipment in general operational areas
	 In the event that any losses/leaks occur near the creek, containment or diversion structures are to be constructed by on site loader using soil/sand/ or other suitable material to prevent migration to the creek
	 If any release from mobile plant onto unsealed soil/surface water is investigated and remediated immediately
	Call service provider to inspect plant & equipment for serviceability
Alarm raising	Any personnel involved or witnessing incident to report to immediate supervisor and PIRMP actions to be implemented.
Emergency	Shaun Jorgensen (reporting to Greg Ninness)
Controller	Call service provider (Shaun Jorgensen)
	Spill Kit manager (Emergency Response Personnel)
Scale of incident	Incident would be localized to the area with no external impact.
Evacuate	Only if fire or explosion potential exists. Site Supervisor and any advice provided by Fire Dept as part of attendance after immediate
	notification.
Communications	Internal:
	Operations Manager
	Greg Ninness
	External mandatory:

Once printed this document is uncontrolled and information only. Refer electronic copy on the Pentarch Group intranet site for controlled version

Document owner: HSE Manager Revision: 11.0 Page 23 of 33
Review date: 03/10/2023 Next review date: 02/10/2025





	Immediate Reporting Contact Sheet to be used
	External non-mandatory: N/A
Rescuer /	As per Site Emergency Plan or Fire Department as part of Immediate Reporting
respondent +	
safety checks	
Rescue + First	As per Site Emergency Plan or Fire Department as part of Immediate Reporting
Aid	
Clean up and	Service Provider to dispose of diesel and advise on required clean-up.
Waste disposal	
Reporting and	See SOPs:
re-preparedness	Incident Management (SOP GRP-OHS-052)

Incident No 8	Mobile plant, hydraulic hose or fuel tank failure from contractors / visitors
	Actions Required (by Shaun Jorgensen and PIRMP Team)
	Contractor/Visitor to notify site representative of issue immediately. (induction)
	Contact all relevant people/department (refer to Immediate Reporting Contact Sheet)
	Area to be restricted to Emergency Response Personnel
	 Ensure spill kit available for any release from mobile plant & equipment in general operational areas
	 If any release from mobile plant onto unsealed soil/surface water is investigated and remediated immediately
	Call service provider to inspect plant & equipment for serviceability
Alarm raising	Any personnel involved or witnessing incident to report to immediate supervisor and PIRMP actions to be implemented.
Emergency	Shaun Jorgensen (reporting to Greg Ninness)
Controller	Call service provider (Shaun Jorgensen)
	Spill Kit manager (Emergency Response Personnel)
Scale of incident	Incident would be localized to the area with no external impact.
Evacuate	Only if fire or explosion potential exists. Site Supervisor and any advice provided by Fire Dept as part of attendance after immediate
	notification.
Communications	Internal:
	Operations Manager
	Greg Ninness

Once printed this document is uncontrolled and information only. Refer electronic copy on the Pentarch Group intranet site for controlled version

Document owner: HSE Manager Revision: 11.0 Page 24 of 33
Review date: 03/10/2023 Next review date: 02/10/2025





	External mandatory:
	Immediate Reporting Contact Sheet to be used
	External non-mandatory: N/A
Rescuer /	As per Site Emergency Plan or Fire Department as part of Immediate Reporting
respondent +	
safety checks	
Rescue + First	As per Site Emergency Plan or Fire Department as part of Immediate Reporting
Aid	
Clean up and	Service Provider to dispose of contaminates.
Waste disposal	
Reporting and	See SOPs:
re-preparedness	Incident Management (SOP GRP-OHS-052)

Incident No 9	Car Park/ fuel tank failure
	Actions Required (by Shaun Jorgensen and PIRMP Team)
	Contractor/Visitor to notify site representative of issue immediately. (induction)
	Area to be restricted to Incident Response Personnel
	Ensure spill kit available for any release from mobile plant
	If any release from mobile plant onto unsealed soil/surface water is investigated and remediated immediately
	Call service provider to inspect plant & equipment
Alarm raising	Any personnel involved or witnessing incident to report to immediate supervisor and PIRMP actions to be implemented.
Emergency	Shaun Jorgensen (reporting to Greg Ninness)
Controller	Spill Kit manager (Emergency Response Personnel)
Scale of incident	Incident would be localized to the area with no external impact.
Evacuate	Only if fire or explosion potential exists. Site Supervisor and any advice provided by Fire Dept as part of attendance after immediate
	notification.
Communications	Internal:
	Operations Manager
	Greg Ninness
	External mandatory:

 $Once \ printed \ this \ document \ is \ uncontrolled \ and \ information \ only. \ Refer \ electronic \ copy \ on \ the \ Pentarch \ Group \ intranet \ site for \ controlled \ version$

Document owner: HSE Manager Revision: 11.0 Page 25 of 33
Review date: 03/10/2023 Next review date: 02/10/2025





	Immediate Reporting Contact Sheet to be used
	External non-mandatory: N/A
Rescuer /	As per Site Emergency Plan or Fire Department as part of Immediate Reporting
respondent +	
safety checks	
Rescue + First	As per Site Emergency Plan or Fire Department as part of Immediate Reporting
Aid	
Clean up and	Service Provider to dispose of contaminate
Waste disposal	
Reporting and	See SOPs:
re-preparedness	Incident Management (SOP GRP-OHS-052)

Incident No 10	Dust from traffic areas				
	Actions Required:				
	Employees, Contractor/Visitor to notify site representative of issue immediately. (induction)				
	Daily monitoring to be undertaken to capture whether and site conditions				
	Contact all relevant people/department (refer to Immediate Reporting Contact Sheet)				
	Dust suppression activity to commence immediately on unsealed roads				
Alarm raising	Any personnel involved or witnessing incident to report to immediate supervisor and PIRMP actions to be implemented.				
Emergency	Shaun Jorgensen (reporting to Greg Ninness)				
Controller	Site Supervisor to instruct site personnel (Shaun Jorgensen)				
Scale of incident	Incident would be localized to the area with no external impact.				
Evacuate	Only if fire or potential exists. Site Supervisor and any advice provided by Fire Dept as part of attendance after immediate				
	notification.				
Communications	Internal:				
	Operations Manager				
	External mandatory:				
	Immediate Reporting Contact Sheet to be used if required				
	External non-mandatory: N/A				

Once printed this document is uncontrolled and information only. Refer electronic copy on the Pentarch Group intranet site for controlled version

Document owner: HSE Manager Revision: 11.0 Page 26 of 33
Review date: 03/10/2023 Next review date: 02/10/2025





Rescuer /	As per Site Emergency Plan or Fire Department as part of Immediate Reporting
respondent +	
safety checks	
Rescue + First	As per Site Emergency Plan or Fire Department as part of Immediate Reporting
Aid	
Clean up and	N/A
Waste disposal	
Reporting and	See SOPs:
re-preparedness	• N/A

Incident No 11	Ongoing Ground Water Monitoring (12 monthly)		
Alarm raising	If ground water monitoring results indicate potential migration off site, National Environmental Manager to be informed.		
Emergency	Shaun Jorgensen (reporting to Greg Ninness)		
Controller			
Scale of incident	Groundwater results to be reviewed by National Environmental Manager for any further action/notification.		
Evacuate	N/A		
Communications	Internal:		
	Operations Manager		
	External mandatory:		
	Immediate Reporting Contact Sheet to be used if required		
	External non-mandatory: N/A		
Rescuer /	N/A		
respondent +			
safety checks			
Rescue + First	N/A		
Aid			
Clean up and	National Environmental Manager to advise		
Waste disposal			
Reporting and	National Environmental Manager to advise		
re-preparedness			

Document owner: HSE Manager Revision: 11.0 Page 27 of 33
Review date: 03/10/2023 Next review date: 02/10/2025





PIRMP Audit

The objectives of an audit are to maintain compliance with this plan. Internal audits of this Plan will be undertaken every 3 years.

Routine testing of the plan will be conducted annually, and can be completed through the following methods:

- Simulated environmental emergency, or
- Desktop simulations.

PIRMP Review

Pentarch Forestry Narooma will review this management plan routinely every 12 months. The Plan review will include:

- This Document, and
- Legislation, Approval and Licence changes.

Events which may trigger a review of this Plan, or its associated documents include:

- Within 1 month of reporting to the nominated parties in accordance with the plan, after a pollution incident, or
- Modification/Improvement to the system

Revisions are to be coordinated by the Site Supervisor and Environmental Representative. The objectives of a review are:

- To maintain compliance with the statutory requirements, and
- To identify opportunities for improvement in the Plan, and reduce the risk to human health and the environment

Once printed this document is uncontrolled and information only. Refer electronic copy on the Pentarch Group intranet site for controlled version

Document owner: HSE Manager

Revision: 11.0

Review date: 03/10/2023

Page 28 of 33 Next review date: 02/10/2025



PENTAR	CH FORESTRY PIRMP NOTIFICATION/ PROC	EDURE RECORD SHEET
	SITE DETAILS	
Site Name	Site Address	Responsible Person
	Notification Procedure	
 Incident to be communicate to 	Greg Ninness immediately (0401895073)	
 GN will consider if incidents req 	uires EPA notification	
 If NOT site supervisor to provide notified 	e periodic updates of incident status to GN for evaluation	on on weather EPA or other parties will need to be
 If Yes GN to call necessary parti 	es of incident and communicate response back to site, G	GN to receive and provide updates to necessary parties
For the coordination of emergency resp	onse teams refer to site emergency procedures.	
	GOVERNMENT AGENCY CONTACT LIST	Г
(document date ar	d time of contact and who contacted) (Police contact is o	only required if considered necessary)
EPA Contact: 131 555	Fire Brigades Contact: 000	Work Cover Contact:
Date and Time:	Date and Time:	Date and Time:
Person making contact:	Person making contact:	Person making contact:
Instructed Actions:	Instructed Actions	Instructed Actions:
Time of arrival	Time of arrival	Time of arrival

Once printed this document is uncontrolled and information only. Refer electronic copy on the Pentarch Group intranet site for controlled version Document owner: HSE Manager Revision: 11.0

Page 29 of 33 Review date: 03/10/2023 Next review date: 02/10/2025



POLLUTION INCIDENT RESPONSE MANAGEMENT PLAN

Local Government Contact:	Department of Health Contact:Base Hospital	Local Police Contact:
After Hours emergency		
	Public Health Unit	
		Date and Time:
	Environmental Health: 149 377	Person making contact:
Date and Time:		Instructed Actions:
Person making contact:	Date and Time:	
Instructed Actions:	Person making contact:	
	Instructed Actions:	
Time of arrival		
	Time of arrival	Time of arrival

Page 30 of 33 Review date: 03/10/2023 Next review date: 02/10/2025



PENTARCH FORESTRY NAROOMA POLLUTION INCIDENT RESPONSE MANAGEMENT PLAN

INCIDENT DETAILS			
Location of Incident:	Emission Type (air, water, land etc.):	Scale of the incident (litres/ m³ involved):	
Date and Time of the Incident:	Internal Persons involved:		
Chemicals /substances involved	I		
Process Involved			
Details of the incident			

Page 31 of 33 Review date: 03/10/2023 Next review date: 02/10/2025



PENTARCH FORESTRY NAROOMA POLLUTION INCIDENT RESPONSE MANAGEMENT PLAN

Main Areas/ sensitive areas of concern e.g. water courses, drains etc.			
OTHER CONTACTS IF REQUIRED Y/N			
Community Group Contact	Neighbor 1	Neighbor 2	
Date and Time:	Date and Time:	Date and Time:	
Person making contact:	Person making contact:	Person making contact:	
Contact method:	Contact method:	Contact method:	
Neighbor 3:	Neighbor 4	Neighbor 5	
Date and Time:	Date and Time:	Date and Time:	
Person making contact:	Person making contact:	Person making contact:	
Contact method:	Contact method:	Contact method:	

Page 32 of 33 Review date: 03/10/2023 Next review date: 02/10/2025



Protocol for industry notification of pollution incidents

Extract from www.environment.nsw.gov.au website

Recent changes to Part 5.7 of the *Protection of the Environment Operations Act 1997* (POEO Act) specify new requirements relating to the notification of pollution incidents.

The changes take effect from 6 February 2012 and require the occupier of premises, the employer or any person carrying on the activity which causes a pollution incident to immediately notify each relevant authority (identified below) when material harm to the environment is caused or threatened. The following information and procedures may assist those responsible for reporting a pollution incident.

Firstly, call 000 if the incident presents an immediate threat to human health or property. Fire and Rescue NSW, the NSW Police and the NSW Ambulance Service are the first responders, as they are responsible for controlling and containing incidents.

If the incident does not require an initial combat agency, or once the 000 call has been made, notify the relevant authorities in the following order. The 24-hour hotline for each authority is given when available:

- the appropriate regulatory authority (ARA) for the activity under the POEO Act (usually the EPA or local authority) the local authority is a local council of an area under the Local Government Act 1993), the Lord Howe Island Board for Lord Howe Island, or the Western Lands Commissioner for the Western Division (except any part of the Western Division within the area of a local council)
- the EPA, if it is not the ARA phone Environment Line on 131 555
- the Ministry of Health via the local Public Health Unit see www.health.nsw.gov.au/publichealth/infectious/phus.asp
- the Work Cover Authority phone 13 10 50
- the local authority if this is not the ARA
- Fire and Rescue NSW phone 000.

The appropriate contact for the relevant local authority and Public Health Unit will vary. All necessary contact numbers should be found in advance and stored for immediate access should a pollution incident need to be notified. These contact numbers should also be identified in the Pollution Incident Response Management Plan prepared for the premises.

Complying with these notification requirements does not remove the need to comply with any other obligations for incident notification, for example, those that apply under other environment protection legislation or legislation administered by Work Cover.

Document owner: HSE Manager Revision: 11.0 Page 33 of 33
Review date: 03/10/2023 Next review date: 02/10/2025