

Pollution Incident Response Management Plan Pentarch Forestry Summerland Way, Koolkhan NSW 2460

Lot 12 DP 818056 EPL 1437

Reviewed 30/09/2024





Local Authority
Clarence Valley Council



Contents

| Overview | 3 |
|---|-------|
| Responsibilities | 3 |
| Training | 3 |
| Testing of the Plan | 3 |
| Incident notification | 4 |
| Definitions | 4 |
| The Plan | 4 |
| Site Map | 5 |
| Storm water and direction of potential overflow areas | 6 |
| Site Assessment | 7-9 |
| External Communications | 10 |
| Risk Assessment Matrix | 10 |
| Risk Assessment on Potential Impacts | 11-14 |
| PIRMP Action Tests | 14-15 |
| PIRMP Training Records | 15 |
| PIRMP Response Actions | 16-28 |
| PIRMP Notification procedure/ Record Sheet | 29-30 |
| Protocol for Industry Notification of pollution incidents | 31 |



Overview

Pentarch Forestry owns and operates a Sawmilling operation and Timber Treatment facility at Summerland Way, Koolkhan in New South Wales. The land totals 31.75 ha and is zoned Industrial 4 (a).

The first plant was constructed in the 1960s and in 1983 Boral absorbed BMI and Allen Taylor. Then a recent acquisition by Pentarch Forestry bought all the Boral Timber operations in 2021 creating the business it is today.

The process involves receiving logs which are sawn into timber. Selected species are treated and then packed and stored in the yard prior to dispatch. The by-products are woodchips and sawdust. 96% of total sawn timber is processed by Pentarch Forestry internally. Treated timber is 48% of the total. E.g. 33,984 m³ of logs yield 9,750 m³ of sawn timber.

The site has a series of dams with the first Tannin dam having the capability of being pumped out and irrigated onto the top of the site when levels are too high. It also has been designed with an overflow drain taking any excess into the first of three residue dams. Each dam, once capacity has been reached, will flow into the next one down. The last dam has been deepened and the lower bank increased to give it more holding capacity. The area surrounding the residue dams is kept well maintained and mown, therefore any concerns with the dam levels or integrity will easily be noticed and acted upon.

The site employees approximately 36 people with operating hours being Monday to Friday. Logs may, however be received over weekends.

Responsibilities

Dan Smith - Site Manager - 02 6644 7280 or 0408723877 Greg Ninness - Regional HSE Manager - 02 6581 9024 or 0401 895 073

Training

All staff must be inducted onto site.

Visitors onto site must be accompanied by an inducted person/employee

All staff must be trained in Emergency Spill Response

All staff must be trained in Emergency Response Procedures

All relevant staff must be trained in the safe use of Dangerous Goods and Hazardous Substances including appropriate PPE

Testing of the Plan

The Plant Manager will be the person responsible for implementing, reviewing, testing and updating the Plan. The Plan will be tested within one month of an environmental incident or annually if no incidents occur within that time period.

A documented drill will be carried out listing what the proposed emergency was, how staff reacted to the emergency, what actions were carried out, what lessons were learnt, and what subsequent actions were entered into RAPID incident reporting system.



Incidents

Following an environmental incident resulting in Material Harm, the five authorities who must be notified immediately are;

- EPA Environment Line 131 555
- Ministry of Health via Public Health Unit Ph: 02 6620 7585.

Pager Service: 1300 555 555. Communicable Disease: 48073. Environmental Health: 149 377. If no answer phone: Mob 0417 244 966 or Mob 0407 904 280

- SafeWork NSW 131 050
- Fire and Rescue NSW ph 000
- Clarence Valley Council 02 6643 0200 a/h 02 6626 6858

A written report will be submitted to the relevant authorities within seven days following a notifiable incident.

Definitions –

Material Harm

Harm to the environment is material if:

- It involves actual or potential harm to the health or safety of human beings or to ecosystems that is not trivial, or
- It results in actual or potential loss or property damage of an amount, or amounts in aggregate, exceeding \$10,000 (or such other amount as is prescribed by the regulations) and
- Loss includes the reasonable costs and expenses that would be incurred in taking all reasonable and practicable measures to prevent, mitigate or make good harm to the environment.

The Plan

This plan will be kept on site and also within the company's database.


The whole plan will be available to an authorized officer on request and to any person responsible for implementing the plan.

The plan, excluding any personal information will be publicly available to any person who makes a written request for it.

Review date: 31/10/2023



SITE PLAN KOOLKHAN



Revision: 3.0 Page 5 of 31
Next review date: 31/10/2025

Review date: 31/10/2023



Figure 2: Storm water and direction of potential overflow areas Legend Stormwater drains Surface flow direction Underground flow

Once printed this document is uncontrolled and information only. Refer electronic copy on the Pentarch Group intranet site for controlled version

Document owner: HSE Manager

Revision: 3.0

Page 6 of 31 Next review date: 31/10/2025



PIRMP Site Assessment Sheet

| Name / description | Covered under Haz Chemicals/MSDS? | Amount stored | Location of storage | Map reference | Need for early warning ¹ | Current controls | See Risk Ass & PIRMP Response Action (see Below) |
|-----------------------|--|---|----------------------|------------------|-------------------------------------|--|--|
| CHEMICALS (raw | materials and product | s which can | cause pollution) | | | | |
| Diesel | Class 3 | 9000ltrs | Maintenance shed | Ref No 1 | N/A | Bunding PMP Training Spill Kits Inductions | Incident # 1-3 |
| Oils/Solvents | Class 3 | Packaged goods up to 1000 Itrs | Maintenance shed | Ref No 2 | N/A | Bunding PMP Training Spill Kits Inductions | Incident # 4 |
| MATERIALS (e.g. | , stockpiles, silos, bulk | solids etc.) | | | | | |
| Log Stock pile | NA | Variable | Dedicated on site | Ref No 6 | Local Bush Fire Brigade | Emergency fire equipment Maintain manageable levels Security | Incident # 5 |
| Woodchip Bins | Refer to Pentarch Forestry's SDS on Woodchip | Variable | Dedicated on site | Ref No 5 | Local Bush Fire Brigade | Emergency fire equipment Maintain manageable levels Security | Incident # 5 |

Document owner: HSE Manager Revision: 3.0 Page 7 of 31
Review date: 31/10/2023 Next review date: 31/10/2025

Once printed this document is uncontrolled and information only. Refer electronic copy on the Pentarch Group intranet site for controlled version

¹ Early warnings relate to informing neighbours who may be affected by the emission of this substance. If this substance is of a type and quantity which may reach neighbours then early warning assessment of actions is required to be undertaken.



Review date: 31/10/2023

| Name / description | Covered under Haz | Amount stored | Location of storage | Map reference | Need for early | Current controls | See Risk Ass & PIRMP Response |
|---------------------------|----------------------|---------------|----------------------|------------------|----------------------------|---|-------------------------------|
| description | Chemicals/MSDS? | Stored | Storage | reference | warning ¹ | | Action (see Below) |
| Residue waste | NA | Variable | Dedicated on site | Ref No 4 | Local Bush Fire Brigade | Emergency fire equipment Maintain manageable levels security | Incident # 5 |
| AQUEOUS (eg da | ms, wastewater tanks | , other wateı | r storage area) | | | | |
| Dam 1 (Tannin) | No | Variable | | Ref No 7 | N/A | Continue to irrigate during windy hot days to maintain levels of dams. Ensure pumps are maintained through Mex maintenance system | Incident # 6 |
| Residue Dam 2 (Tannin) | No | Variable | | Ref No 7 | N/A | Continue to irrigate during windy hot days to maintain levels of dams. Ensure pumps are maintained through Mex maintenance system | Incident # 6 |
| Residue Dam 3 (Tannin) | No | Variable | | Ref No 7 | N/A | Continue to irrigate during windy hot days to maintain levels of dams. Ensure pumps are maintained through Mex maintenance system | Incident # 6 |
| Residue Dam 4 (Tannin) | No | Variable | | Ref No 7 | N/A | Continue to irrigate during windy hot days to maintain levels of dams. | Incident # 6 |

Page 8 of 31 Next review date: 31/10/2025



| Name / description | Covered under Haz Chemicals/MSDS? | Amount stored | Location of storage | Map reference | Need for early warning ¹ | Current controls | See Risk Ass & PIRMP Response Action (see Below) |
|--|---|--------------------------------|----------------------|------------------|-------------------------------------|--|--|
| | | | | | | Ensure pumps are maintained through Mex maintenance system | |
| Mobile plant (onsite) | Class 3 | Up to 8 Mobile Plant Vehicles | Dedicated on site | MA NA | N/A | Spill Kits Pre start checks PMP Training | Incident # 7 |
| Mobile plant (onsite) Contractor/visitor | Class 3 | Variable | Dedicated on site | NA | N/A | Spill KitsPre startTrainingInductions | Incident # 8 |
| Car Parking up to 30 vehicles | Class 3 | Variable | Site Office | Ref No 9 | N/A | Spill KitsTraining | Incident # 9 |
| Traffic areas (dust, chem. leaks & loss | Class 3 | NA | Dedicated on site | Site map | N/A | TrainingWater cartSpill KitsBunding/drainage | Incident # 10 |
| Treatment facility | | Variable | Treatment tank | Ref No #3 | | Bunding PMP Training Spill Kits Inductions | Incident # 13 |

Page 9 of 31 Next review date: 31/10/2025



| IMPACT ON NEIGHBOURS ASSESSMENT – EARLY WARNINGS | | | | | | | | |
|--|------------------------|--------------------|-------------|-----------------|---|--------------------------|--|--|
| Site Name | | | | Responsible per | rson | Date | | |
| Koolkhan | | | Site Manage | r: Dan Smith | 29/02/2024 | | | |
| HSE & Production Manager: Todd | | | | | | | | |
| | | | | Ford | - | | | |
| Incident | External Release (air, | Neighbours | Communi | cation | Actions and other co | ntrol measures | | |
| type/description | waterway etc) | impacted/extent of | methods | | (eg posting on website, community group meetings) | | | |
| | | impact | Early warr | nings | | | | |
| Dust off site | Air | | Phone | | | | | |
| Smoke from burning fire | Air | | Phone | | | | | |
| Release from tannin dams | Waterway | | Phone/Em | ail | Notify HSE Manager v | ria email (Greg Ninness) | | |

RISK ASSESSMENT MATRIX

| | | Likelihood of environmental harm occurring | | | | | |
|---|----------|--|-------------|-------------|--|--|--|
| | | Certain | Likely | Less likely | | | |
| Level of potential environmental impact | High | Code red | Code red | Code orange | | | |
| | Moderate | Code red | Code orange | Code yellow | | | |
| | Low | Code orange | Code yellow | Code yellow | | | |

Once printed this document is uncontrolled and information only. Refer electronic copy on the Pentarch Group intranet site for controlled version

Document owner: HSE Manager

Review date: 31/10/2023

Page 10 of 31 Next review date: 31/10/2025



RISK ASSESSMENT on POTENTIAL IMPACTS

| | Hazard and Likelihood Risk Assessment and Corrective Control Measures | | | | | | | | | |
|---|---|-----------------|-------------|------|-----------------------------------|---|-----------------------------|------------------|--|--|
| Pentarch For Koolkhan | estry Site | | | - | ble Person Managers | Review Date 29 th February 2024 | | | | |
| Name / ref of pollutant/ chemicals | Description of Hazard / Incident leading to hazard | Level of impact | Likelihood | Risk | Impact on neighbours ² | Control Measures Corrective Action Coverage under other Plans | Responsible person | Action date | | |
| Diesel | Incident #1 Catastrophic failure of above ground tank (9000ltrs) | Low | Less likely | | N/A | Consequence: (Low): Failure resulting in loss of all or substantial volume of tank would be captured entirely by existing bund and no release to soil or water. Bund capacity 13,000L. Likelihood: (Less likely): Due to location within bund, damage to tanks is unlikely to occur from external equipment. In addition tank is maintained in good structural integrity with low risk of failure through corrosion. | As per PIRMP action plan | When required | | |
| | Incident #2 Loss of diesel outside bund during refuelling/ fuelling operations. | Moderate | Less likely | | N/A | Consequence: (Moderate): Failure resulting in loss of all or substantial volume of tanks would be captured entirely by secondary bund and minimal release to soil. Likelihood: (Less likely): Due to location within the bund an incident while re-fuelling & fuelling is unlikely to occur. In addition, hoses and refuelling equipment are maintained in good structural integrity with low risk of failure. | As per PIRMP action plan | When required | | |

² If the incident may impact on neighbours then it will need to trigger the early warnings assessment and actions

Once printed this document is uncontrolled and information only. Refer electronic copy on the Pentarch Group intranet site for controlled version

Document owner: HSE Manager Revision: 3.0 Page 11 of 31
Review date: 31/10/2023 Next review date: 31/10/2025



| | Incident #3 Loss of fuel within bunded area with leaking or open drain valve | Low | Less Likely | N/A | Consequence: (Low): Failure resulting in loss of all or substantial volume of tanks would be captured entirely by secondary bund and minimal release to soil. Likelihood: (Less likely): Drain valve, hoses and refuelling equipment are maintained in good structural integrity with low risk of failure The drain valve is locked at all times. | As per PIRMP action plan | When required |
|--|--|-----|-------------|-----|--|-----------------------------|------------------|
| Oils/ Solvents | Incident #4 Loss of oils solvents inside bund during delivery and or use | Low | Less Likely | N/A | Consequence: (Low): Failure resulting in loss of oils/solvents from packaged goods would be captured entirely by existing bund and no release to soil or water. Likelihood: (Less likely): Due to location within the bund, delivery & use is unlikely to occur. In addition, hoses and decanting equipment are maintained in good structural integrity with low risk of failure. | As per PIRMP action plan | When required |
| Log, Wood chip & Residue stockpiles | Incident #5. Spontaneous combustion or ignited fire | Low | Less Likely | Υ | Consequence: (Low): Fire from stock piles causing loss of assets creating substantial smoke around the area Likelihood: (Less likely): Stockpiles are maintained to a manageable level along with emergency equipment maintained on a monthly basis. Security monitors site activities 24hrs a day | As per PIRMP action plan | When required |
| Dams 1-4 | Incident #6 Catastrophic failure of one or more tannin dams releasing large volumes of tannin water into on-site and off- site water courses (i.e. creeks? River). | Low | Less Likely | Υ | Consequence: (Low): Catastrophic failure of one or more tannin dams are likely to result in off-site impacts to water courses which would predominantly reduce water quality over a short period of time. As such, impact to the environment/human health is not considered to be significant. Likelihood: (Less likely): Dams are frequently monitored and inspected for levels and integrity. Note: For PIRMP purposes overflow events during extreme wet weather will be reported under POEO Licence obligations and not Immediate Reporting. | As per PIRMP action plan | When required |

Document owner: HSE Manager
Revision: 3.0
Page 12 of 31
Review date: 31/10/2023
Next review date: 31/10/2025



| Mobile Plant | Incident #7 Mobile plant, hydraulic hose or fuel tank failure | Low | Less Likely | N | Consequence: (Low): Failure from fuel tank or hydraulic hoses would be contained to a small localised area on site. Likelihood: (Less likely): Hose or fuel tank failure from mobile plant would be minimal as prestart and regular maintenance programs are in place to capture and prevent such occurrences. Spills kits also maintained and available in various areas. | As per PIRMP action plan | When required |
|--|---|-----|-------------|---|--|-----------------------------|------------------|
| Mobile plant/ Contractor, Visitor | Incident # 8 Mobile plant, hydraulic hose or fuel tank failure | Low | Less Likely | N | Consequence: (Low): Failure from fuel tank or hydraulic hoses would be maintain to a small localised area on site. Likelihood: (Less likely): Hose or fuel tank failure from mobile plant would be minimal as prestart and regular maintenance programs are in place to capture and prevent such occurrences. Spills kits also maintained and available in various areas. Inductions for all contractors stating their accountabilities and responsibilities for reporting environmental incidents. | As per PIRMP action plan | When required |
| Car Park | Incident # 9 Ruptured fuel tank Oil/fuel/diesel/co olant leaks | Low | Less Likely | N | Consequence: (Low): Failure from fuel tank or hydraulic hoses would be contained to a small localised area on site. Likelihood: (Less likely): Hose or fuel tank failure from mobile plant would be minimal as prestart and regular maintenance programs are in place to capture and prevent such occurrences. Spills kits also maintained and available in various areas | As per PIRMP action plan | When required |
| Traffic areas (dust) | Incident # 10 Surface dust from mobile plant | Low | Less Likely | Υ | Consequence: (Low): Dust created from continuous mobile plant operations across site Likelihood:(Less likely): A fully maintained water cart will be utilised in high wind conditions | As per PIRMP action plan | When required |

Document owner: HSE Manager Revision: 3.0 Page 13 of 31
Review date: 31/10/2023 Next review date: 31/10/2025



| Onsite treatment | Incident # 13 Catastrophic | Low | Less Likely | N | Consequence :(Low): Failure resulting in loss of chemicals from treatment tank would be captured on site | As per PIRMP | When |
|------------------|-----------------------------------|-----|-------------|----|--|--------------|----------|
| facility | failure of door seal/tank failure | LOW | Less Likely | ., | Likelihood :(Less likely): Treatment tanks are frequently monitored and inspected for levels and integrity. | action plan | required |

Action Test Records

| Plans Test Date: 21 / 03 / 2013 | Incident Tested: No. 4 - Loss off oil/solvents, packaged goods See Incident Report Date xx/xx/xx. | Comments: : See report |
|---------------------------------|--|---------------------------|
| Plans Test Date: 28 / 01 / 2014 | Incident Tested: No 4 Loss of hydraulic fluid to surrounding areas under equipment. | : See report |
| Plans Test Date: 08 / 07 / 2015 | Incident Tested: No.2 The simulated incident scenario used for this event was to test a site contractor's ability to react to an emergency oil spill | : See report |
| Plans Test Date: 26 / 05 / 2016 | Incident Tested: No.8 Containment of treatment facility spill | : See Report |
| Plans Test Date: 31 / 10 / 2018 | Incident Tested: No.4 - Loss off oil/solvents. The incident was used to test site employee's ability to react to an emergency oil spill. | : See Report |
| Plans Test Date: 16 / 10 / 2019 | Incident Tested: No. 4 - Loss off oil/solvents, packaged goods See Incident Report Date 01/11/2019 | : See Report |
| Plans Test Date: 14 / 10 / 2020 | Incident Tested: No. 4 - Loss off oil/solvents, packaged goods See Incident Report Date 28/10/2020 | : See Report |
| Plans Test Date: 01 / 09 / 2021 | Incident Tested: No 4 Loss off oil/solvents, packaged goods See Incident Report Date 03/11/2021 | : See Report |

Once printed this document is uncontrolled and information only. Refer electronic copy on the Pentarch Group intranet site for controlled version

Document owner: HSE Manager

Revision: 3.0

Review date: 31/10/2023

Page 14 of 31 Next review date: 31/10/2025



| Plans Test Date: 03 / 08 / 2022 | Incident Tested : No.9 The simulated incident scenario used for this event was to test a site contractor's ability to react to an emergency oil spill | : See Report |
|---------------------------------|--|--------------|
| Plans Test Date: 31 / 10 / 2023 | Incident Tested: No.4 - Loss off oil/solvents. The incident was used to test site employee's ability to react to an emergency oil spill. | : See Report |
| Plans Test Date: 30/09/ 2024 | Incident Tested : No.2 Loss of Fuel due to filling and refueling from one/both diesel tanks, see incident report dated 30.09.24 | : See Report |

| PIRMP Based Training | | | | |
|---------------------------------|----------------|-----------|------------------------|-------------------------|
| Training | Next Scheduled | Completed | Provider | Targeted Audience |
| PIRMP Awareness | May 2013 | Υ | A.Balazs G. Ninness | Supervisors |
| PIRMP Awareness | May 2013 | Y | A.Balazs G. Ninness | Operational Employees |
| Emergency Response (general) | June 2014 | Y | 3 rd Party | Emergency Response Team |
| Emergency Response (i.e. Fire) | June 2015 | Υ | 3rd Party | Operational Employees |
| Environmental Awareness | August-2016 | Υ | G. Ninness | Operational Employees |
| Emergency Response (general) | November-2018 | Y | S. Taylor | Operational Employees |
| Environmental Training | October 2019 | Υ | MLS | Operational Employees |
| Environmental Training | December 2020 | N | MLS | Operational Employees |
| Environmental Training | December 2022 | Υ | G. Ninness | Operational Employees |
| Environmental Training | March 2025 | N | G.Ninness | |

Page 15 of 31 Next review date: 31/10/2025

PIRMP RESPONSE ACTIONS

Incident No 1

| Incident No 1 | Catastrophic failure of diesel tanks. |
|-------------------|---|
| | Actions Required: |
| | Contact all relevant people/department (refer to Immediate Reporting Contact Sheet) |
| | Ensure bunds are capturing full volume of diesel |
| | Ensure bund integrity is sound throughout the entire period of incident (i.e. periodic inspections) |
| | Contact service provider (Caltex No. 1800033111 or Transpacific 02 96007185) to pump-out bund contents |
| | Area to be restricted to Incident Response Personnel |
| | Ensure spill kit available for any release from bund |
| | If any release from bund onto unsealed soil/surface water - Environmental Consultants to be engaged to investigate and remediate contamination. |
| | Repair/replace tanks |
| | Refuel tanks |
| | Inspect bund for ongoing serviceability |
| Alarm raising | Any personnel involved or witnessing incident to report to immediate supervisor and PIRMP actions to be implemented. |
| Emergency | Site Manager (reporting to Greg Ninness – HSE Timber 0401895073 |
| Controller | Call service provider (Site Manager) |
| | Spill Kit manager (Supervisor) |
| | Periodic inspections and update reporting of site and bund (Site Manager) |
| Scale of incident | Incident would be restricted to chemical storage area with minimal external impact. However, potential for bund overflow or failure may |
| | result in soil and surface water contamination that will require specialist investigation/remediation. |
| Evacuate | Only if fire or explosion potential exists. Plant Manager and any advice provided by Fire Dept as part of attendance after immediate |
| | notification. |
| Communications | Site Manager / Supervisor to call Greg Ninness 0401 895 073 (available on 24 hours basis) and provide information as detailed in the PENTARCH FORESTRY PIRMP Notification Record Sheet. Greg must be periodically updated with respect to incident status until situation is controlled and no on-going human or environmental threat exists. |
| | Greg to consider threat to human health risks when receiving incident status updates. If high risk is identified Attila or Greg will provide guidance |
| | on further communication requirements to relevant parties. |
| | Communications procedures for coordinating relevant authorities refer to site emergency procedures |

Once printed this document is uncontrolled and information only. Refer electronic copy on the Pentarch Group intranet site for controlled version

Document owner: HSE Manager

Revision: 3.0

Document owner: HSE Manager Revision: 3.0 Page 16 of 31
Review date: 31/10/2023 Next review date: 31/10/2025



| Rescuer / | As per Site Emergency Plan or Fire Department as part of Immediate Reporting |
|-----------------|--|
| respondent + | |
| safety checks | |
| Rescue + First | As per Site Emergency Plan or Fire Department as part of Immediate Reporting |
| Aid | |
| Clean up and | Service Provider to dispose of diesel and advise on required clean-up. |
| Waste disposal | |
| Reporting and | See SOPs: |
| re-preparedness | Incident Investigation GRP-OHS-052 |
| | Emergency Planning and Response GRP-OHS-053 |

Incident No 2

| Incident No 2 | Loss of Fuel due to filling and refueling from one/both diesel tanks. |
|---------------|---|
| | Actions Required: |
| | Contact all relevant people/department (refer to Immediate Reporting Contact Sheet) |
| | Ensure bunds are capturing full volume of diesel |
| | Ensure bund integrity is sound throughout the entire period of incident (i.e. periodic inspections) |
| | Contact service provider (Caltex No. 1800033111 or Transpacific 02 96007185) to pump-out bund contents |
| | Area to be restricted to Incident Response Personnel |
| | Ensure spill kit available for any release from bund |
| | If any release from bund onto unsealed soil/surface water - Environmental Consultants to be engaged to investigate and remediate contamination. |
| | Repair/replace tanks |
| | Refuel tanks |
| | Inspect bund for ongoing serviceability |
| Alarm raising | Any personnel involved or witnessing incident to report to immediate supervisor and PIRMP actions to be implemented. |
| Emergency | Site Manager (reporting to Greg Ninness – HSE Timber 0401895073) |
| Controller | Call service provider (Site Manager) |
| | Spill Kit manager (Supervisor) |
| | Periodic inspections and update reporting of site and bund (Site Manager) |

Page 17 of 31 Review date: 31/10/2023 Next review date: 31/10/2025



PENTARCH FORESTRY - KOOLKHAN

POLLUTION INCIDENT RESPONSE MANAGEMENT PLAN

| Scale of incident | Incident would be restricted to chemical storage area with minimal external impact. However, potential for bund overflow or failure may |
|-------------------|---|
| | result in soil and surface water contamination that will require specialist investigation/remediation. |
| Evacuate | Only if fire or explosion potential exists. Plant Manager and any advice provided by Fire Dept as part of attendance after immediate |
| | notification. |
| Communications | Site Manager / Supervisor to call Greg Ninness 0401 895 073 (available on 24 hours basis) and provide information as detailed in the PENTARCH FORESTRY PIRMP Notification Record Sheet. Greg must be periodically updated with respect to incident status until situation is controlled and no on-going human or environmental threat exists. Greg to consider threat to human health risks when receiving incident status updates. If high risk is identified Attila or Greg will provide guidance on further communication requirements to relevant parties. |
| | Communications procedures for coordinating relevant authorities refer to site emergency procedures |
| Rescuer / | As per Site Emergency Plan or Fire Department as part of Immediate Reporting |
| respondent + | |
| safety checks | |
| Rescue + First | As per Site Emergency Plan or Fire Department as part of Immediate Reporting |
| Aid | |
| Clean up and | Service Provider to dispose of diesel and advise on required clean-up. |
| Waste disposal | |
| Reporting and | See SOPs: |
| re-preparedness | Incident Investigation GRP-OHS-052 |
| - • - | Emergency Planning and Response GRP-OHS-053 |

Incident No 3

| Incident No 3 | Failure of drain valve on bund | | |
|---------------|--|--|--|
| | Actions Required: | | |
| | Contact all relevant people/department (refer to Immediate Reporting Contact Sheet) | | |
| | Ensure bunds are capturing full volume of diesel | | |
| | Ensure bund integrity is sound throughout the entire period of incident (i.e. periodic inspections) | | |
| | Contact service provider (Caltex No. 1800033111 or Transpacific 02 96007185) to pump-out bund contents | | |
| | Area to be restricted to Incident Response Personnel | | |
| | Ensure spill kit available for any release from bund | | |
| | If any release from bund onto unsealed soil/surface water - Environmental Consultants to be engaged to investigate and remediate | | |
| | contamination. | | |
| | Repair/replace tanks | | |

Once printed this document is uncontrolled and information only. Refer electronic copy on the Pentarch Group intranet site for controlled version Document owner: HSE Manager Revision: 3.0

Page 18 of 31 Review date: 31/10/2023 Next review date: 31/10/2025



PENTARCH FORESTRY - KOOLKHAN

POLLUTION INCIDENT RESPONSE MANAGEMENT PLAN

| | Refuel tanks |
|-----------------------|---|
| | Inspect bund for ongoing serviceability |
| Alarm raising | Any personnel involved or witnessing incident to report to immediate supervisor and PIRMP actions to be implemented. |
| Emergency | Site Manager (reporting to Greg Ninness – HSE Timber 0401895073) |
| Controller | Call service provider (Site Manager) |
| | Spill Kit manager (Supervisor) |
| | Periodic inspections and update reporting of site and bund (Site Manager) |
| Scale of incident | Incident would be restricted to chemical storage area with minimal external impact. However, potential for bund overflow or failure may result in soil and surface water contamination that will require specialist investigation/remediation. |
| Evacuate | Only if fire or explosion potential exists. Plant Manager and any advice provided by Fire Dept as part of attendance after immediate notification. |
| Communications | Site Manager / Supervisor to call Greg Ninness 0401 895 073 (available on 24 hours basis) and provide information as detailed in the PENTARCH FORESTRY PIRMP Notification Record Sheet. Greg must be periodically updated with respect to incident status until situation is controlled and no on-going human or environmental threat exists. Greg to consider threat to human health risks when receiving incident status updates. If high risk is identified Attila or Greg will provide guidance on further communication requirements to relevant parties. Communications procedures for coordinating relevant authorities refer to site emergency procedures |
| Rescuer / | As per Site Emergency Plan or Fire Department as part of Immediate Reporting |
| respondent + | |
| safety checks | |
| Rescue + First Aid | As per Site Emergency Plan or Fire Department as part of Immediate Reporting |
| Clean up and | Service Provider to dispose of diesel and advise on required clean-up. |
| Waste disposal | |
| Reporting and | See SOPs: |
| re-preparedness | Incident Investigation GRP-OHS-052 |
| · · | Emergency Planning and Response GRP-OHS-053 |

Once printed this document is uncontrolled and information only. Refer electronic copy on the Pentarch Group intranet site for controlled version Document owner: HSE Manager Revision: 3.0

Page 19 of 31 Review date: 31/10/2023 Next review date: 31/10/2025

Incident No 4

| Incident No 4 | Loss of oil/solvents, packaged goods |
|-------------------|---|
| | Actions Required: |
| | Contact all relevant people/department (refer to Immediate Reporting Contact Sheet) |
| | Ensure bunds are capturing full volume of oil/solvents |
| | Ensure bund integrity is sound throughout the entire period of incident (i.e. periodic inspections) |
| | • Contact service provider (Caltex No. 1800033111or Transpacific 02 96007185) to pump-out bund contents |
| | Area to be restricted to Incident Response Personnel |
| | Ensure spill kit available for any release from bund |
| | • If any release from bund onto unsealed soil/surface water - Environmental Consultants to be engaged to investigate and remediate contamination. |
| | Inspect bund for ongoing serviceability |
| Alarm raising | Any personnel involved or witnessing incident to report to immediate supervisor and PIRMP actions to be implemented. |
| Emergency | Site Manager (reporting to Greg Ninness – HSE Timber 0401895073) |
| Controller | Call service provider (Site Manager) |
| | Spill Kit manager (Supervisor) |
| | Periodic inspections and update reporting of site and bund (Site Manager) |
| Scale of incident | Incident would be restricted to chemical storage area with minimal external impact. However, potential for bund overflow or failure may result in soil and surface water contamination that will require specialist investigation/remediation. |
| Evacuate | Only if fire or explosion potential exists. Plant Manager and any advice provided by Fire Dept as part of attendance after immediate notification. |
| Communications | Site Manager / Supervisor to call Greg Ninness 0401 895 073 (available on 24 hours basis) and provide information as detailed in the PENTARCH FORESTRY PIRMP Notification Record Sheet. Greg must be periodically updated with respect to incident status until situation is controlled and no on-going human or environmental threat exists. |
| | Greg to consider threat to human health risks when receiving incident status updates. If high risk is identified Attila or Greg will provide guidance on further communication requirements to relevant parties. |
| | Communications procedures for coordinating relevant authorities refer to site emergency procedures |
| Rescuer / | As per Site Emergency Plan or Fire Department as part of Immediate Reporting |
| respondent + | |
| safety checks | |

Document owner: HSE Manager Revision: 3.0 Page 20 of 31
Review date: 31/10/2023 Next review date: 31/10/2025



| Rescue + First | As per Site Emergency Plan or Fire Department as part of Immediate Reporting |
|-----------------|--|
| Aid | |
| Clean up and | Service Provider to dispose of diesel and advise on required clean-up. |
| Waste disposal | |
| Reporting and | See SOPs: |
| re-preparedness | Incident Investigation GRP-OHS-052 |
| | Emergency Planning and Response GRP-OHS-053 |

Incident No 5

| Incident No 5 | Fire in stockpiles of Logs, woodchip and waste residue |
|-------------------|--|
| | Actions Required: • Contact all relevant people/departments (refer to Immediate Reporting Contact Sheet) |
| | Area to be restricted to Incident Response Personnel |
| | Environmental Consultants to be engaged to investigate and remediate contamination if required |
| Alarm raising | Any personnel involved or witnessing incident to report to immediate supervisor and PIRMP actions to be implemented. |
| Emergency | Site Manager (reporting to Greg Ninness – HSE Timber 0401895073) |
| Controller | Site Emergency Response Wardens |
| | Call Emergencies services |
| | Periodic inspections and update reporting of site (Site Manager) |
| Scale of incident | Incident would be restricted to storage area with minimal external impact. However, potential for offsite ambers and/or smoke that will |
| | require specialist investigation/remediation. |
| Evacuate | Only if fire or explosion poses potential harm to personnel or structures. Plant Manager and any advice provided by Fire Dept as part of attendance after immediate notification. |
| Communications | • Site Manager / Supervisor to call or Greg Ninness 0401 895 073 (available on 24 hours basis) and provide information as detailed in the PENTARCH FORESTRY PIRMP Notification Record Sheet. Greg must be periodically updated with respect to incident status until situation is controlled and no on-going human or environmental threat exists. |
| | Greg to consider threat to human health risks when receiving incident status updates. If high risk is identified Attila or Greg will provide guidance |
| | on further communication requirements to relevant parties. |
| | Communications procedures for coordinating relevant authorities refer to site emergency procedures |

Once printed this document is uncontrolled and information only. Refer electronic copy on the Pentarch Group intranet site for controlled version Document owner: HSE Manager Revision: 3.0

Page 21 of 31 Review date: 31/10/2023 Next review date: 31/10/2025



| Rescuer / | As per Site Emergency Plan or Fire Department as part of Immediate Reporting |
|-----------------|--|
| respondent + | |
| safety checks | |
| Rescue + First | As per Site Emergency Plan or Fire Department as part of Immediate Reporting |
| Aid | |
| Clean up and | As required pending severity. |
| Waste disposal | |
| Reporting and | See SOPs: |
| re-preparedness | Incident Investigation GRP-OHS-052 |
| | Emergency Planning and Response GRP-OHS-053 |

Incident No 6

| Incident No 6 | Failure of one or more tannin dams | |
|-------------------|--|--|
| | Actions Required: | |
| | Contact all relevant people/department (refer to Immediate Reporting Contact Sheet) | |
| | Ensure dam integrity is sound throughout the entire period of incident (i.e. periodic inspections) | |
| | Contact local neighbors if going to be in inundated by rise of water. Contact to be made with Greg Ninnes also | |
| | Area to be restricted to Incident Response Personnel | |
| | Contact local contractor to rebuild dams immediately | |
| Alarm raising | Any personnel involved or witnessing incident to report to immediate supervisor and PIRMP actions to be implemented. | |
| Emergency | Site Manager (reporting to Greg Ninness – HSE Timber 0401895073) | |
| Controller | Call Emergencies services | |
| | Periodic inspections and update reporting of site (Site Manager) | |
| Scale of incident | Catastrophic failure of one or more tannin dams are likely to result in off-site impacts to water courses which would predominantly reduce | |
| | water quality over a short period of time. As such, impact to the environment/human health is not considered to be significant. | |
| Evacuate | Only if harm potential exists. Plant Manager and any advice provided by Fire Dept/Hazmat as part of attendance after immediate | |
| | notification. | |
| Communications | Site Manager / Supervisor to call Greg Ninness 0401 895 073 (available on 24 hours basis) and provide information as detailed in the PENTARCH | |
| | FORESTRY PIRMP Notification Record Sheet. Greg must be periodically updated with respect to incident status until situation is controlled and no | |
| | on-going human or environmental threat exists. | |

Page 22 of 31 Review date: 31/10/2023 Next review date: 31/10/2025



PENTARCH FORESTRY - KOOLKHAN

POLLUTION INCIDENT RESPONSE MANAGEMENT PLAN

| | Greg to consider threat to human health risks when receiving incident status updates. If high risk is identified Attila or Greg will provide guidance on further communication requirements to relevant parties. | | |
|-----------------|--|--|--|
| | Communications procedures for coordinating relevant authorities refer to site emergency procedures | | |
| Rescuer / | As per Site Emergency Plan as part of Immediate Reporting | | |
| respondent + | | | |
| safety checks | | | |
| Rescue + First | As per Site Emergency Plan or First aid officers as part of Immediate Reporting | | |
| Aid | | | |
| Clean up and | Consultants to be contacted to advise on required clean-up. | | |
| Waste disposal | | | |
| Reporting and | See SOPs: | | |
| re-preparedness | Incident Investigation GRP-OHS-052 | | |
| | Emergency Planning and Response GRP-OHS-053 | | |

Incident No 7

| Incident No 7 | Mobile plant, hydraulic hose or fuel tank failure | | | |
|-------------------|--|--|--|--|
| | Actions Required: | | | |
| | Contact all relevant people/department (refer to Immediate Reporting Contact Sheet) | | | |
| | Area to be restricted to Incident Response Personnel | | | |
| | Ensure spill kit available for any release from mobile plant & equipment | | | |
| | If any release from mobile plant onto unsealed soil/surface water is investigated and remediated immediately | | | |
| | Call service provider to inspect plant & equipment for serviceability | | | |
| Alarm raising | Any personnel involved or witnessing incident to report to immediate supervisor and PIRMP actions to be implemented. | | | |
| Emergency | Site Manager (reporting to Greg Ninness – HSE Timber 0401895073) | | | |
| Controller | Call service provider (Site Manager) | | | |
| | Spill Kit manager (operator) | | | |
| Scale of incident | Incident would be localized to the area with no external impact. | | | |
| Evacuate | Only if fire or explosion potential exists. Plant Manager and any advice provided by Fire Dept as part of attendance after immediate | | | |
| | notification. | | | |

Once printed this document is uncontrolled and information only. Refer electronic copy on the Pentarch Group intranet site for controlled version Document owner: HSE Manager Revision: 3.0

Page 23 of 31 Review date: 31/10/2023 Next review date: 31/10/2025



| Communications | Site Manager / Supervisor to call Greg Ninness 0401 895 073 (available on 24 hours basis) and provide information as detailed in the PEN FORESTRY PIRMP Notification Record Sheet. Greg must be periodically updated with respect to incident status until situation is controlled on-going human or environmental threat exists. Greg to consider threat to human health risks when receiving incident status updates. If high risk is identified Attila or Greg will provide gon further communication requirements to relevant parties. Communications procedures for coordinating relevant authorities refer to site emergency procedures | | |
|--|---|--|--|
| Rescuer / respondent + safety checks | As per Site Emergency Plan or Fire Department as part of Immediate Reporting | | |
| Rescue + First Aid | As per Site Emergency Plan or Fire Department as part of Immediate Reporting | | |
| Clean up and Waste disposal | Service Provider to dispose of diesel and advise on required clean-up. | | |
| Reporting and re-preparedness | See SOPs: Incident Investigation GRP-OHS-052 Emergency Planning and Response GRP-OHS-053 | | |

Incident No 8

| Incident No 8 | Mobile plant, hydraulic hose or fuel tank failure from contractors / visitors | | | |
|-------------------|--|--|--|--|
| | Actions Required: | | | |
| | Contractor/Visitor to notify site representative of issue immediately. (induction) | | | |
| | Contact all relevant people/department (refer to Immediate Reporting Contact Sheet) | | | |
| | Area to be restricted to Incident Response Personnel | | | |
| | Ensure spill kit available for any release from mobile plant & equipment | | | |
| | If any release from mobile plant onto unsealed soil/surface water is investigated and remediated immediately | | | |
| | Call service provider to inspect plant & equipment for serviceability | | | |
| Alarm raising | Any personnel involved or witnessing incident to report to immediate supervisor and PIRMP actions to be implemented. | | | |
| Emergency | Site Manager (reporting to Greg Ninness – HSE Timber 0401895073) | | | |
| Controller | Call service provider (Site Manager) | | | |
| | Spill Kit manager (operator) | | | |
| Scale of incident | Incident would be localized to the area with no external impact. | | | |

Once printed this document is uncontrolled and information only. Refer electronic copy on the Pentarch Group intranet site for controlled version Document owner: HSE Manager Revision: 3.0

Page 24 of 31 Review date: 31/10/2023 Next review date: 31/10/2025



| Evacuate | Only if fire or explosion potential exists. Plant Manager and any advice provided by Fire Dept as part of attendance after immediate notification. | | |
|-----------------|---|--|--|
| Communications | Site Manager / Supervisor to call Greg Ninness 0401 895 073 (available on 24 hours basis) and provide information as detailed in the PENTARCH FORESTRY PIRMP Notification Record Sheet. Greg must be periodically updated with respect to incident status until situation is controlled and no on-going human or environmental threat exists. Greg to consider threat to human health risks when receiving incident status updates. If high risk is identified Attila or Greg will provide guidance on further communication requirements to relevant parties. Communications procedures for coordinating relevant authorities refer to site emergency procedures | | |
| Rescuer / | As per Site Emergency Plan or Fire Department as part of Immediate Reporting | | |
| respondent + | | | |
| safety checks | | | |
| Rescue + First | As per Site Emergency Plan or Fire Department as part of Immediate Reporting | | |
| Aid | | | |
| Clean up and | Service Provider to dispose of contaminates. | | |
| Waste disposal | | | |
| Reporting and | See SOPs: | | |
| re-preparedness | Incident Investigation GRP-OHS-052 | | |
| I | Emergency Planning and Response GRP-OHS-053 | | |

Incident No 9

| Incident No 9 | Car Park/ fuel tank failure | | | |
|-------------------|--|--|--|--|
| | Actions Required: | | | |
| | Contractor/Visitor to notify site representative of issue immediately. (induction) | | | |
| | Area to be restricted to Incident Response Personnel | | | |
| | Ensure spill kit available for any release from mobile plant | | | |
| | If any release from mobile plant onto unsealed soil/surface water is investigated and remediated immediately | | | |
| | Call service provider to inspect plant & equipment | | | |
| Alarm raising | Any personnel involved or witnessing incident to report to immediate supervisor and PIRMP actions to be implemented. | | | |
| Emergency | Site Manager (reporting to Greg Ninness – HSE Advisor Timber 0401895073) | | | |
| Controller | Spill Kit manager (site personnel) | | | |
| Scale of incident | Incident would be localized to the area with no external impact. | | | |

Once printed this document is uncontrolled and information only. Refer electronic copy on the Pentarch Group intranet site for controlled version

Document owner: HSE Manager

Revision: 3.0

Review date: 31/10/2023



| Fugginate. | Only if fire ar explosion notantial exists. Plant Manager and any advice provided by Fire Dept as part of attendance after immediate | | | |
|-----------------|---|--|--|--|
| Evacuate | Only if fire or explosion potential exists. Plant Manager and any advice provided by Fire Dept as part of attendance after immediate | | | |
| | notification. | | | |
| Communications | Site Manager / Supervisor to call Greg Ninness 0401 895 073 (available on 24 hours basis) and provide information as detailed in the PENTARCH FORESTRY PIRMP Notification Record Sheet. Greg must be periodically updated with respect to incident status until situation is controlled and no on-going human or environmental threat exists. Greg to consider threat to human health risks when receiving incident status updates. If high risk is identified Attila or Greg will provide guidance on further communication requirements to relevant parties. Communications procedures for coordinating relevant authorities refer to site emergency procedures | | | |
| Rescuer / | As per Site Emergency Plan or Fire Department as part of Immediate Reporting | | | |
| respondent + | | | | |
| safety checks | | | | |
| Rescue + First | As per Site Emergency Plan or Fire Department as part of Immediate Reporting | | | |
| Aid | | | | |
| Clean up and | Service Provider to dispose of contaminate | | | |
| Waste disposal | | | | |
| Reporting and | See SOPs: | | | |
| re-preparedness | Incident Investigation GRP-OHS-052 | | | |
| - | Emergency Planning and Response GRP-OHS-053 | | | |

Incident No 10

| Incident No 10 | Dust from traffic areas | | | |
|-------------------|---|--|--|--|
| | Actions Required: | | | |
| | Employees, Contractor/Visitor to notify site representative of issue immediately. (induction) | | | |
| | Daily monitoring to be undertaken to capture whether and site conditions | | | |
| | Contact all relevant people/department (refer to Immediate Reporting Contact Sheet) | | | |
| | Dust suppression activity to commence immediately on unsealed roads | | | |
| Alarm raising | Any personnel involved or witnessing incident to report to immediate supervisor and PIRMP actions to be implemented. | | | |
| Emergency | Site Manager (reporting to Greg Ninness – HSE Advisor Timber 0401895073) | | | |
| Controller | Site operations manager to instruct site personnel | | | |
| Scale of incident | Incident would be localized to the area with little to no external impact | | | |
| Evacuate | Only if harm potential exists. Plant Manager and any advice provided by Fire Dept as part of attendance after immediate notification. | | | |

Document owner: HSE Manager Page 26 of 31 Revision: 3.0 Review date: 31/10/2023 Next review date: 31/10/2025



| Communications | Site Manager / Supervisor to call Greg Ninness 0401 895 073 (available on 24 hours basis) and provide information as detailed in the PENTARCH FORESTRY PIRMP Notification Record Sheet. Greg must be periodically updated with respect to incident status until situation is controlled and no on-going human or environmental threat exists. Greg to consider threat to human health risks when receiving incident status updates. If high risk is identified Attila or Greg will provide guidance on further communication requirements to relevant parties. Communications procedures for coordinating relevant authorities refer to site emergency procedures |
|--|---|
| Rescuer / respondent + safety checks | As per Site Emergency Plan as part of Immediate Reporting |
| Rescue + First Aid | As per Site Emergency Plan as part of Immediate Reporting |
| Clean up and Waste disposal | N/A |
| Reporting and re-preparedness | See SOPs: • N/A |

Incident No 11

| Incident No 13 | Loss of chemical from treatment facility | | | |
|----------------|--|--|--|--|
| | Actions Required: | | | |
| | Contact all relevant people/department (refer to Immediate Reporting Contact Sheet) | | | |
| | Ensure tank & area integrity is sound throughout the entire period of incident (i.e. periodic inspections) | | | |
| | Contact service provider Osmose Chemicals 0419711775 or 0887231399 for an emergency | | | |
| | Area to be restricted to Incident Response Personnel | | | |
| | Ensure spill kit available for any release from area | | | |
| | If any release from area onto unsealed soil/surface water - Environmental Consultants to be engaged to investigate and remediate | | | |
| | contamination. | | | |
| | Inspect transformer for ongoing serviceability | | | |
| Alarm raising | Any personnel involved or witnessing incident to report to immediate supervisor and PIRMP actions to be implemented. | | | |
| Emergency | Site Manager (reporting to Greg Ninness – HSE Advisor Timber 0401895073) | | | |
| Controller | Call service provider (Site Manager) | | | |
| | Spill Kit manager (Supervisor) | | | |
| | Periodic inspections and update reporting of site (Site Manager & operator) | | | |

Once printed this document is uncontrolled and information only. Refer electronic copy on the Pentarch Group intranet site for controlled version Document owner: HSE Manager Revision: 3.0

Document owner: HSE Manager Revision: 3.0 Page 27 of 31
Review date: 31/10/2023 Next review date: 31/10/2025



PENTARCH FORESTRY - KOOLKHAN

POLLUTION INCIDENT RESPONSE MANAGEMENT PLAN

| lent would be restricted to chemical storage area with minimal external impact. However, potential for bund overflow or failure may it in soil and surface water contamination that will require specialist investigation/remediation. If fire or explosion potential exists. Plant Manager and any advice provided by Fire Dept as part of attendance after immediate | | | |
|---|--|--|--|
| if fire or explosion potential exists. Plant Manager and any advice provided by Fire Dept as part of attendance after immediate | | | |
| | | | |
| tarata | | | |
| notification. | | | |
| • Site Manager / Supervisor to call Greg Ninness 0401 895 073 (available on 24 hours basis) and provide information as detailed in the PENTARCH FORESTRY PIRMP Notification Record Sheet. Greg must be periodically updated with respect to incident status until situation is controlled and no on-going human or environmental threat exists. | | | |
| • Attila or Greg to consider threat to human health risks when receiving incident status updates. If high risk is identified Attila or Greg will provide | | | |
| guidance on further communication requirements to relevant parties. | | | |
| munications procedures for coordinating relevant authorities refer to site emergency procedures | | | |
| As per Site Emergency Plan or Fire Department as part of Immediate Reporting | | | |
| | | | |
| | | | |
| As per Site Emergency Plan or Fire Department as part of Immediate Reporting | | | |
| | | | |
| Service Provider to dispose of contaminants and advise on required clean-up. | | | |
| | | | |
| See SOPs: | | | |
| Incident Investigation GRP-OHS-052 | | | |
| Incident Investigation GRP-OHS-052 Emergency Planning and Response GRP-OHS-053 | | | |
| i | | | |

Page 28 of 31 Review date: 31/10/2023 Next review date: 31/10/2025



| PENTARCH FORESTRY PIRMP NOTIFICATION/ PROCEDURE RECORD SHEET | | | |
|--|---------------------|-----------|--|
| SITE DETAILS | | | |
| Site Name Site Address Responsible Person | | | |
| Pentarch Forestry Koolkhan | 43 Mill Rd Koolkhan | Dan Smith | |

Notification Procedure

- Incident to be communicate to Greg Ninness immediately (0401895073)
- GN will consider if incidents requires EPA notification
- If NOT site supervisor to provide periodic updates of incident status to GN for evaluation on whether EPA or other parties will need to be notified
- If Yes GN to call necessary parties of incident and communicate response back to site, GN to receive and provide updates to necessary parties

For the coordination of emergency response teams refer to site emergency procedures.

| (document data and time of cor | GOVERNMENT AGENCY CONTACT LIST stact and who contacted) (Police contact is only requ | ired if considered necessary) |
|--|--|-----------------------------------|
| EPA Contact: 131 555 | Fire Brigades Contact: 000 | WorkCover Contact: 66591700 |
| Date and Time: | Date and Time: | Date and Time: |
| Person making contact: | Person making contact: | Person making contact: |
| Instructed Actions: | Instructed Actions | Instructed Actions: |
| | | |
| Time of arrival | Time of arrival | Time of arrival |
| Local Government Contact: 02 66430200 | Department of Health Contact: Base Hospital 02 66402222 | Local Police Contact: 66420222 |
| After Hours emergency | Base Hospital 02 00402222 | 00420222 |
| 0266266858 | Public Health Unit Lismore Office | |
| | Environmental Health: 149 377 | |
| Date and Time: | Date and Time: | Date and Time: |
| Person making contact: | Person making contact: | Person making contact: |
| Instructed Actions: | Instructed Actions: | Instructed Actions: |
| | | |
| | | |
| | | |
| Time of arrival | Time of arrival | Time of arrival |
| | | |

Once printed this document is uncontrolled and information only. Refer electronic copy on the Pentarch Group intranet site for controlled version

Document owner: HSE Manager
Revision: 3.0
Page 29 of 31
Review date: 31/10/2023
Next review date: 31/10/2025



| PENTARCH FORESTRY PIRMP NOTIFICATION/ PROCEDURE RECORD SHEET | | | | |
|---|--|--|--|--|
| INCIDENT DETAILS | | | | |
| Location of Incident: | Emission Type (air, water, land etc): | Scale of the incident (litres/ m³ involved): | | |
| Date and Time of the Incident: | Internal Persons involved: | | | |
| Chemicals /substances involved | | | | |
| Process Involved | | | | |
| | | | | |
| Details of the incident | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| Main Areas/ sensitive areas of concern e.g. water courses, drains etc | | | | |
| main ricus, sensitive areas or consern eig. we | ace, courses, arams etc | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| OTHER CONTACTS IF REQUIRED Y/N | | | | |
| Community Group Contact | Neighbour 1 | Neighbour 2 | | |
| Date and Time: | Date and Time: | Date and Time: | | |
| Person making contact: | Person making contact: | Person making contact: | | |
| Contact method: | Contact method: | Contact method: | | |
| Neighbour 3: | Neighbour 4 | Neighbour 5 | | |
| Date and Time: | Date and Time: | Date and Time: | | |
| Person making contact: Contact method: | Person making contact: Contact method: | Person making contact: Contact method: | | |
| 25 | - Contact method | SSSSC Method. | | |



Protocol for industry notification of pollution incidents

Extract from www.environment.nsw.gov.au website

Recent changes to Part 5.7 of the *Protection of the Environment Operations Act 1997* (POEO Act) specify new requirements relating to the notification of pollution incidents.

The changes take effect from 6 February 2012 and require the occupier of premises, the employer or any person carrying on the activity which causes a pollution incident to immediately notify each relevant authority (identified below) when material harm to the environment is caused or threatened. The following information and procedures may assist those responsible for reporting a pollution incident.

Firstly, call 000 if the incident presents an immediate threat to human health or property. Fire and Rescue NSW, the NSW Police and the NSW Ambulance Service are the first responders, as they are responsible for controlling and containing incidents.

If the incident does not require an initial combat agency, or once the 000 call has been made, notify the relevant authorities in the following order. The 24-hour hotline for each authority is given when available:

- the appropriate regulatory authority (ARA) for the activity under the POEO Act (usually the EPA or local authority) the local authority is a local council of an area under the Local Government Act 1993), the Lord Howe Island Board for Lord Howe Island, or the Western Lands Commissioner for the Western Division (except any part of the Western Division within the area of a local council)
- the EPA, if it is not the ARA phone Environment Line on 131 555
- the Ministry of Health via the local Public Health Unit see www.health.nsw.gov.au/publichealth/infectious/phus.asp
- the WorkCover Authority phone 13 10 50
- the local authority if this is not the ARA
- Fire and Rescue NSW phone 000.

The appropriate contact for the relevant local authority and Public Health Unit will vary. All necessary contact numbers should be found in advance and stored for immediate access should a pollution incident need to be notified. These contact numbers should also be identified in the Pollution Incident Response Management Plan prepared for the premises.

Complying with these notification requirements does not remove the need to comply with any other obligations for incident notification, for example, those that apply under other environment protection legislation or legislation administered by WorkCover.